



Date/Time: 19.04.2022 09:08

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4197627

JC NO 305512996

CUSTOMER  
VMS CITYCAB PTE LTD  
CUSTOMER NO 7010070  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
L. (R) 65551188 (C)  
(P)

|              |                   |                               |
|--------------|-------------------|-------------------------------|
| REGN NO      | SHC 421H          | MILEAGE                       |
| MAKE         | HYUNDAI           | FUEL                          |
| MODEL        | IONIQ(G2)         | E. 1/2 F                      |
| YR OF MANU   | 30.04.2019        | DATE/TIME IN 18.04.2022 16:00 |
| CHASSIS CODE | KMHC851CVKU141318 | TARGET DATE                   |
|              |                   | COMPLETION DATE/TIME          |


COUNT CARD NO

JOB DESCRIPTION

Accident Date: 17.04.2022  
NATURE: 3P 17.04.2022

| S/NO   | LABOR CODE |
|--------|------------|
| 000020 | PB         |
| 000030 | SP         |

DESCRIPTION  
PANEL BEATING  
SPRAYPAINT CHARGE



CHECKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

No.: SHC 421H JU NTUC

Vehicle No.: SHC 421H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 19.04.2022

Time: 09:07:14

Page: 1

NIM (CAS)

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305512996  
REGN NO : SHC 421H  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 30.04.2019  
DATE/TIME IN : 18.04.2022 16:00  
ACCIDENT DATE : 17.04.2022

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-0594-G DEP MIRROR ASSY-OUTSIDE R 1 1,391.70 20.00 1,113.36

SUB-TOTAL : 1,113.36

## JOB NATURE

0000 PB PANEL BEATING 120.00 /

0001 SP SPRAYPAINT CHARGE 120.00 /

SUB-TOTAL : 240.00

TOTAL : 1,353.36

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Theron  
19/4/22 @  
01 days. claim.