

ASSIGNMENT

NS/INC22003743/Vqc

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. MT/1169149-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S
	X

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH/9495D Yr Regn: S/7 IR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Ionig c.c. 1580
 Colour: blue A/C: Insured / Std / NI / NA
 Sp. Reading: 427962 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHLC851CVJU103431
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 195/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 18/4/22 D.O.I. 19/4/22 1605
 Survey held at CDGE
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>no GJA provided</u>
	<u>Thevan finalised LS \$1250, 2 days. (Red \$1207.70, 49%)</u>

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

1) 12/05 Typist ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : TP

Lump Sum / L.B.I. (\$) 1250

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____) ☐ : Interview (\$ _____) ☐ : Tech. Invs (\$ _____) ☐ : Weekend (\$ _____)


Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____
 TOTAL _____

Date/Time: 19.04.2022 13:32 Page : 1

Job: ARC Repair TP(CLS0)1	JOB CARD Sales Order: 4197798	JC NO 305513033
OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 (P) 65508755 (O) (P)	REGN NO: SH 9495D MAKE: HYUNDAI MODEL: IONIQ(G2) YR OF MANU: 05.07.2018 CHASSIS CODE: KMHC851CVJU103431	MILEAGE FUEL E 1/2 F DATE/TIME IN 19.04.2022 10:50 TARGET DATE COMPLETION DATE/TIME:
UNIT CARD NO.		

cident Date: 18.04.2022
TURE: 3P 18.04.2022

NO 0010	LABOR CODE PB	DESCRIPTION LUMP SUM REPAIR-SH 9495D-TP
------------	------------------	--



ED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
dgement Slip		Exit Pass	
Vehicle No.: SH 9495D		LIMTS	
Service Advisor		Signature/Date	
Name of Service Advisor		Date	
To be kept by Security Guard			

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 19.04.22MODEL: Hyundai IoniqINSURANCE: NTUC (LIS)VEHICLE NO.: SH 9495DMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Under Moulding	1		\$ 155.00
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper Foglamp	1		\$ 201.50
	SUB TOTAL			\$ 1,782.75
	LESS 20%			\$ 356.55
	DISCOUNTED TOTAL			\$ 1,426.20
	Reverse Sensors	1		\$ 180.00
	Rear No. Plate With Trim Cover	1		\$ 55.00
	SUB NETT TOTAL			\$ 235.00
	LESS 10%			\$ 23.50
	NETT TOTAL			\$ 211.50
	SPARE PARTS TOTAL			\$ 1,637.70
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 2,457.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair order will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan

92235769

19/4/22 16:45

LIS 2 days up