

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3348C

Make : HYUNDAI

Model : IONIQ(G3)

Date: 14/04/2022

Insurance: NTUC

MVA: MS. LOKE YY

P/P.

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKER RH			\$ 28.00
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50
1	HEADLAMP RH			\$ 2,110.30
1	DAY LIGHT RH			\$ 642.50
1	FRT BUMPER SIDE MOULDING RH			\$ 93.60
1	FRT FENDER RH			\$ 588.80
1	FRT FENDER SHEILD RH			\$ 164.70
1	EMBLEM - BLUE DRIVE RH			\$ 26.60
1	FRT WHEEL HUB CAP RH			\$ 177.70
			346.40	
	SUB TOTAL			\$ 4,703.80
	LESS 20%			\$ 940.76
	DISCOUNTED TOTAL			\$ 3,763.04
				\$ -
	Labour Charge			
	PANEL BEATING			\$ 1,050.00
	SPRAY PAINTING CHARGE			\$ 800.00
	TUFF KOTE			\$ 60.00
	CHECK ALL LIGHTING			\$ 60.00
	TOTAL LABOUR			\$ 1,970.00
	ESTIMATE TOTAL			\$ 5,733.04
				5868

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thavan
82235704
14/4/22 1630
P/P 3clay swp

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: