

Ass. PLO. BY:

REP:

CS/SMO 22003758/Any3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFB2112R Yr Regn: 2011, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E250 c.c. 1796

Colour: silver Grey A/C: Insured / Std / NI / NA

Sp. Reading: 176587 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120472A398935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R17

R: 245/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 25/04/22

Survey held at People

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sampo.
	Lump Sum \$1750 and 2 days
	(Red. \$840, 32%)
	MV: 88K
	PV: 42.7K
	Nett: 45.3K.

Date/Time, File Pass to?

1) 13/7/22

Date/Time, File Return to?

2) _____



Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Test drive (\$)



Other (\$)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

Report Formed:

TP

Lump Sum

\$1750

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

033Z

Vehicle Details

Vehicle No.:

SFB2112R

Vehicle to be Exported:

No

Intended Deregistration Date:

25 Apr 2022

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

E 250CGI

Primary Colour:

Silver

Manufacturing Year:

2011

Engine No.:

27186030199415

Chassis No.:

WDD2120472A398935

Maximum Power Output:

150.0 kW (201 bhp)

Open Market Value:

\$53,800.00

Original Registration Date:

20 Apr 2011

First Registration Date:

20 Apr 2011

Transfer Count:

2

Actual ARF Paid:

\$53,800.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 Mar 2031

COE Category:

E - Open Category

COE Period(Years):

10

PQP Paid:

\$47,701.00

COE Rebate Amount:

\$42,610.00

Total Rebate Amount:**\$42,610.00**

The information contained herein is correct as at 25 Apr 2022

OK