

Our Job Ref No : 305513262
Date : 28.04.2022

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC7367K

21.04.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2. The repair job shall bill to: CHINA GBL1528B
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$950.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Thuvan

Date : 28/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7367K

MAKE REG 18.10.2018

DATE 21.04.2022

MODEL : HYUNDAI IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT FENDER RH			\$588.80
1	FRONT FENDER EMBLEM			\$26.60
	SUB TOTAL			\$615.40
	LESS 20%			\$123.08
	DISCOUNTED TOTAL			\$492.32
1	FRONT FENDER ADVERTISEMENT			\$100.00
	Labour Charge			\$100.00
	Panel Beating			\$350.00
	Spray Painting Charge			\$300.00
	TOTAL LABOUR			\$650.00
	ESTIMATE TOTAL			\$1,242.32

Thuan
82235469
21/4/22 1715
L/S 2dayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.