

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s KANG CAR REPAIRERS

of

Insured:

Policy No. D20MFL0000637_02

Claims No. MFL2022D0002089


Sum Insured: Excess: -

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$7000

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBN7901G

Yr Regn: 10 Dec/2018

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YBR125 c.c 124

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 81781.7 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LBPRES1022J0010566 *

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ norder / Jammed / Leaked / Burnt or

Brake: ☒ norder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TIMSUN

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. 6/4/2022 D.O.I. 25-04-2022

Survey held at 178 PAYA LEBAR ROAD 5:20PM

Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/4/22 Insured withdraw OD claim

29/4/22 Submit preli report-revised fig \$2940.87

Date/Time, File Pass to?

☒ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2) 29/4/22-typist

Report Filed at

Long Quid / MPB

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : A/Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other:

TOTAL