



Not Notified  
 11 Days @  
 Recovery After Paint  
 5 days

**TSR AUTOMOTIVE PTE LTD**

Date : 25/04/2022

QUOTATION -THIRD PARTY CLAIM

AXA INSURANCE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim  
 Veh. No : YQ 1838 H  
 Model : ISUZU NPR 85  
 Insured Ins: ERGO INSURANCE

Accident on : 25/04/2022

QTY	PARTICULARS	AMOUNT	SURVEYOR
<b>Your Insurer Vehicle No : SHC 1333 Y</b>			
1	FRONT DOOR LH	\$ 2,985.00	✓
1	FRONT DOOR HINGES LH	\$ 480.00	X
1	FRONT DOOR LOCK LH	\$ 424.50	X
1	FRONT DOOR WEATHERSTRIP LH	\$ 385.60	?
1	FRONT DOOR LOWER RUBBER LH	\$ 225.00	✓
1	FRONT STEP GARNISH LH	\$ 464.50	✓
1	FRONT CORNER PANEL LH	\$ 685.60	✓
1	FRONT CORNER PANEL RUBBER LH	\$ 98.00	✓
1	FRONT CORNER PANEL BRACKET LH	\$ 160.00	?
1	HEADLAMP LH	\$ 1,685.00	✓
1	HEADLAMP BRACKET LH	\$ 220.00	?
1	HEADLAMP LOWER RUBBER LH	\$ 268.00	✓
1	HEADLAMP PANEL LH	\$ 580.00	X
1	SIGNAL LAMP LH	\$ 480.00	✓
1	FRONT GRILLE	\$ 788.50	X
1	FRONT BUMPER LH	\$ 1,485.90	✓
1	FRONT BUMPER BRACKET LH	\$ 220.00	✓
1	FRONT BUMPER INNER BEAM	\$ 680.00	?
		\$ 11,635.60	
	Less 10 %	\$ <del>2,000.00</del>	
		\$ 8,726.70	
<b>S/NETT PARTS</b>			
1	FRONT COMPANY LOGO LH	\$ 500.00	15000
1	FRONT BIZSAFE 3 STICKER LH	\$ 300.00	8000
	<b>TOTAL . SIN</b>	\$ 800.00	
	<b>TOTAL PARTS :</b>	\$ 9,526.70	

110022901kg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## TSR AUTOMOTIVE PTE LTD

Date : 25/04/2022

### QUOTATION -THIRD PARTY CLAIM

AXA INSURANCE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim  
 Veh. No : YQ 1838 H  
 Model : ISUZU NPR 85  
 Insured Ins: ERGO INSURANCE  
 SURVEYOR

Accident on : 25/04/2022

QTY	LABOUR	AMOUNT	
	Balance b/f	\$ 9,526.70	
	<u>LABOUR CHARGES</u>		
	Labour charges to do cutting welding , replace repair accident affected area	\$ 1,200.00	<i>600</i>
	To remove refix garbish , side trim upholstery etc for accident damage repair	\$ 200.00	<i>60</i>
	To transfer door parts to another door	\$ 140.00	<i>60</i>
	Check lamp wiring system, focus lamp etc	\$ 120.00	
	To do anti rust	\$ 60.00	<i>30</i>
	To do spray painting for accident affected area	\$ 800.00	<i>700</i>
	Total Labour :	\$ 2,520.00	
	Total Parts & Labour :	\$ 12,046.70	
	<b>GRAND TOTAL :</b>	<b>\$ 12,046.70</b>	

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please read carefully the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder under the Authorized Signer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The cover and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. All cases reported must be referred to the Police for investigation.
6. This report will be reviewed by the Insurance of the GIA Process Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the completion of this report by the insured, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	25/04/2022 13:49 (SGT)
Date of Accident	25/04/2022 09:27 (SGT)
Exact Location of Accident	MacPherson, Singapore
Additional Location Information	MACPHERSON TOWARDS BENDEMEER
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	YQ1838H
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	LBL CONSTRUCTION PTE LTD
Company Reg No	2XXXX273C
Email Address	ANDY.LEE@PAS.SG
Mobile Phone No	(Phone) +65-84345507
Alternative Phone No	+65-84345507

## VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	NPR85UH5A 3.0 MT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2999

## INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCG21014490
Cover Note Number	-

## DRIVER

Name of Driver	GOVINTHARAJ BALAMURUGAN
Passport No/FIN	GXXXX628N



A - TO NORTH  
 B - TO WEST

STATEMENT OF THE ACCIDENT

My vehicle moving straight,  
 tax came out from minor road and hit  
 onto my vehicle front left side and door.  
 My lane after yellow box empty at the  
 time of accident.

We and my passengers suffer Injury, have not  
 see doctor or make Police report.

Attach Some Photo.

DECLARATION

I hereby declare the foregoing facts are true and correct to the best of my knowledge and belief.

[Signature]      [Signature]      [Signature]  
 Date: 11/11/2023      Date: 11/11/2023      Date: 11/11/2023