

PRS

ASSIGNMENT

CS3/CTI22003826/Gty3

From:

Date:

Veh No:

FBT4143R

Yr Regn: 15 Feb/2022

Estimated Cost:

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP ☒ / S / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

HONDA / ADV750

c.c 745

at Workshop m/s

ADVANCE REPUBLIC

Colour:

White

A/C: Insured / Std / NI / NA

of

Sp.Reading

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JH2RH10AXMK013791 *

Claims No.

Gen. Cond:

☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:

☒ norder / Jammed / Leaked / Burnt or

(Client's Record)

Brake:

☒ norder / Jammed / Leaked / Burnt or

Make of Veh:

Modi:

☒ Nil / Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	N/S	O/S

Bal. or Market Value: \$20k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

25-04-2022

Survey held at

W/S

4:45PM

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1000 - \$2000

SUBMIT PRS REPORT

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: W/Weekend (\$

3 + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: