



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22003856/Epa3q2 Date: 13/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMZ 4273L	Veh. Inspected	SLE 7740H
	Policy No.	P2434658	Coverage (\$)	0.00
	Claim No.	S2M03Z9M	Excess (\$)	0.00
	Assign From		Assign Date	26/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MNTBBAB17Z0027557	Colour	SILVER
	Odometer	49730 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	GOODYEAR	5 mm
	L/H Front Tyre	205/55 R16	GOODYEAR	5 mm
	R/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
	L/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/04/2022	Inspection Date	26/04/2022
	Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	