

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

STRIDES AUTOMOTIVE SERVICES PTE LTD	1/Eny3e2
Code: SMR	
Insured Veh. SHF 180L Veh. Inspected SNA 8423P Policy No. Coverage (\$) 0.00 Claim No. TAX/04/22/2071 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/04/2022 Vehicle Particulars & Condition	
Insured Veh. SHF 180L Veh. Inspected SNA 8423P	
Policy No. Coverage (\$) 0.00 Claim No. TAX/04/22/2071 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/04/2022 2. Vehicle Particulars & Condition	
Claim No. TAX/04/22/2071 Excess (\$) 0.00 Assign From HUA YEN Assign Date 26/04/2022 Vehicle Particulars & Condition	
Assign From HUA YEN Assign Date 26/04/2022 Vehicle Particulars & Condition	
2. Vehicle Particulars & Condition	
Make & Model MINI ONE C. 1499	
Wake & Woder Willy Old	
Engine No. HIDDEN Year of Reg. 2021	
Chassis No. WMW22DK0402R01333 Colour RED	
Odometer 14684 KM Steering IN ORDER	
Brakes IN ORDER Modification SPORTS RIM	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 205/45 R17 MICHELIN 5 mm	
L/H Front Tyre 205/45 R17 MICHELIN 5 mm	
R/H Rear Tyre 205/45 R17 MICHELIN 5 mm	
L/H Rear Tyre 205/45 R17 MICHELIN 5 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 23/04/2022 Inspection Date 27/04/2022	
Survey held at 27A TANJONG PENJURU	
Repairer EUROKARS HABITAT PTE LTD	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days	