



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: YVONNE ANG

Ref: CS/ASM22003910/Kvy3s2  
Date: 26/05/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLZ 2108G	<b>Veh. Inspected</b>	SLE 3058X
<b>Policy No.</b>	GA350254	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03ZEU	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANG Yvonne	<b>Assign Date</b>	27/04/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	RU11200668	<b>Colour</b>	METALLIC GREEN
<b>Odometer</b>	111757 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	YOKOHAMA	9 mm
<b>L/H Front Tyre</b>	215/60 R16	YOKOHAMA	9 mm
<b>R/H Rear Tyre</b>	215/60 R16	YOKOHAMA	9 mm
<b>L/H Rear Tyre</b>	215/60 R16	YOKOHAMA	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	23/04/2022	<b>Inspection Date</b>	27/04/2022
<b>Survey held at</b>	CHOON HOCK MOTOR TRADING CO BLK 176 SIN MING DRIVE #05-03 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**