

ASS. REC. BY:

REF: ASM / 22 00 3910 1KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chom Hock

of _____

Insured: SLZ 2108G

Policy No. _____

Claims No. S2M03ZEU

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: 856k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLZ 3058X Yr Regn: 07, 16

Type: M.Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: M. Green A/C: Insured / Std / NI / NA

Sp. Reading: 111757 T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: RU1 - 1200688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 9 mm

Rear R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 23/4/22

D.O.I. 27/4/2022
10:30am

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 181 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| 18/5/22 | Kenneth informed LS \$2500 (Red 1449.92, 36%) |

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

1) _____
2) 18/5/22-typist

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

S - RS. \$ _____

Fixes _____

Others _____

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format: TP

Lump Sum / H.B.t: (\$ 2500)

Total Parts & ... 2,260.00

CHOON HOCK MOTOR TRADING CO

25 April 2022

*NOT Authorized
 6/1/22 &
 Recovery After Pain
 3 days*

ESTIMATE REPAIR BILL ON SLE 3058X HONDA VEZEL AUTO

| | | | |
|---------------------------------------|----------------|-------------|---|
| 1 pce front headlamp RH | | \$ 1,999.30 | ? |
| 1 pce front bumper assy. | <i>M</i> | \$ 466.20 | ✓ |
| 1 pce front bumper reinforcement | | \$ 257.40 | ? |
| 1 pce front bumper fog light cover RH | <i>Red</i> | \$ 25.90 | ✓ |
| 1 pce front bumper fog light RH | | \$ 237.90 | ? |
| 1 pce front bumper lid RH | <i>Bul/Dri</i> | \$ 212.70 | ✓ |
| 1 pce front fender arch garnish RH | <i>Dis</i> | \$ 150.60 | ✓ |
| 1 pce front retainer RH | <i>CM</i> | \$ 12.40 | ✓ |
| | | \$ 3,362.40 | |
| less 20% | | \$ 672.48 | |
| | | \$ 2,689.92 | |

Labour

| | | |
|----------------|-------------|-------------|
| Wiring | \$ 60.00 | <i>2d</i> |
| Panel beating | \$ 600.00 | <i>300d</i> |
| Spray painting | \$ 600.00 | <i>400d</i> |
| Total amount : | \$ 3,949.92 | NETT |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
 Tel: (65) 64530778 Email: choonhockmotor@gmail.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|--|
| Date of Submission | 25/04/2022 17:54 (SGT) |
| Date of Accident | 23/04/2022 10:30 (SGT) |
| Exact Location of Accident | 73 Compassvale Bow, Singapore 544995 |
| Additional Location Information | THE QUARTZ CONDOMINIUM, 73 COMPASSVALE BOW |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SLE3058X |
| INSURED/POLICYHOLDER | |
| Is company? | No |
| Name Of Registered Owner | TAN THIANG YEW MICHEAL |
| NRIC No | SXXXX756B |
| Email Address | MIKETYTAN@GMAIL.COM |
| Mobile Phone No | (Phone) +65-91788821 |
| Alternative Phone No | (Home) +65-91788821 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Honda |
| Model | Vezele |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1496 |

INSURANCE COMPANY

| | |
|---------------------------|-------------------------------------|
| Name of Insurance Company | Sompo Insurance Singapore Pte. Ltd. |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | D21MTPV01009700 |
| Cover Note Number | 15/07/2021 TO 14/07/2022 |

DRIVER

| | |
|----------------|------------------------|
| Name of Driver | TAN THIANG YEW MICHEAL |
| NRIC No | SXXXX756B |

SKETCH PLAN

Sompo
Vehicle: SLE 3058 X
25/04/2022

IMPORTANT NOTICE

- 1. Please report accurately the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the judgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Sketch Plan



[Handwritten Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



[Handwritten Signature]

Witnessed by Reporting Centre Personnel

25/04/2022