

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM22003920/Rea3q2
	8 SHENTON WAY AXA TOWERSING			Date:	18/08/2022
	ATTN:WINNIE			Code:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMR 191H	Veh. Inspected	l	SJW 2870C
	Policy No.	GA557930	Coverage (\$)		0.00
	Claim No.	S2M03ZJ8	Excess (\$)		0.00
	Assign From		Assign Date		27/04/2022
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3 1.6L SDN LUX	c.c		1598
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	JM6BL10Z1A0117126	Colour		WHITE
	Odometer	139358 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	ROTALLA		6 mm
	L/H Front Tyre	205/55 R16	ROTALLA		6 mm
	R/H Rear Tyre	205/55 R16	ROTALLA		6 mm
	L/H Rear Tyre	205/55 R16	ROTALLA		6 mm
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/04/2022	Inspection Dat	е	27/04/2022
	Survey held at	JEMENTAH MOTOR WORKS			
		BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		12 Worl	king Days