

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SPORTS MOTOR

of

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$5500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBM4018G

Yr Regn: 30 Oct/2013

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PIAGGIO VESPA GTS 300 SUPER c.c 278

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 90654.8

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZAPM4520000076613 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-12

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. mm

L/Bal. mm

D.O.A.

D.O.I. 27-04-2022

Survey held at

W/S

3:30PM

Des. of Damages: ☒ Frt / Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: