

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s AUTO INSURE

of

Insured:

Policy No:

Claims No. SNM22D202523/C01

Sum Insured: Excess: \$450

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value: \$67k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBK1245Y

Yr Regn: 27 Dec/2019

Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: RENAULT / KANGOO 1.5 c.c 1461

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: —

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1FWT8H363265096 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 28-04-2022

Survey held at W/S 11:30

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop orThe ☒ U/C / ☒ Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Total Rebate Amount \$18,147

29/04/22@1.28pm revert to Chee So Chow via Merimen.

12/05/22@3.42pm Pauline Tham informed C/A via Merimen.

12/05/22@3.42pm Informed Wksp C/A & ex:\$450 by email.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long. Cdn / MPB: