



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

### ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIRD PARTY

Vehicle No. : FBK6029Y

Make & Model : HONDA CB400X

Year of Manufacture : \_\_\_\_\_

Chassis No. : \_\_\_\_\_

Ins Company : FIRST CAPITAL

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : D-21097290MFCE/103

Date of Accident : 20/06/2021

Time of Accident : '06:45 HRS

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

#### **Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 43,140.00

Plus/Less \_\_\_\_\_ \$ -

Total of Cost / List \$ 43,140.00

(b) Nett Price Items \$ 938.00

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 43,140.00

Labour (Appendix B) \$ 1,800.00

Total Repair Cost \$ 44,940.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor :

Company :

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_