



Your Ref: 2022 22004659SL

Date: 27th June 2022

Our Ref: CS6/AIS22003945/Tvy3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01

Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SCG 380E ACCIDENT ON 24/04/2022

We thank you for your instruction on 27/04/2022.

The following vehicle information was recorded:

Registration Number	: SCG 380E
Make & Model	: Nissan X-Trail 2.0 CVT
Chassis Number	: JN1JANT32Z0011981
Year of Registration	: 2019
Engine Capacity	: 1997 cc

1. The vehicle sustained damages at the n/s body. (Details see photographs enclosed)
2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.