



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003957/Tvy3e2 Date: 09/01/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMN 8194T	Veh. Inspected	SLM 520E	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014918/CD	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	27/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY 1.5	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHGM6660HP000536	Colour	GREY	
Odometer	145792 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	WEST LAKE	6 mm	
L/H Front Tyre	185/55 R16	WEST LAKE	6 mm	
R/H Rear Tyre	185/55 R16	WEST LAKE	6 mm	
L/H Rear Tyre	185/55 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2022	Inspection Date	28/04/2022	
Survey held at	BLK 1 KAKI BUKIT AVE 6 #01-08 AUTOBAY @ KB			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	