

ASS. REC. BY:

REF:

C12 / 220039711KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$61K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: SLA2910M
Repairer Reference: A0407
Date calculated: 25/04/2022 11:24 AM

Full Report
Registration: SLA2910M
Printed: 25/04/2022 11:24 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	SLA2910M	Date of Incident:	14/04/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	WISH(ZGE21L/ZGE2)		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 W2 01		
Registration:	SLA2910M		
VIN number:	JTDGG20W50J003688		
Odometer:			
Model Specs			
AIR CONDITIONING	FOG LAMPS	1.8 LTR 95 KW	PROD JAPAN
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Not Authorized
1/1/2022
Meaning After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Code	Description	WU	Price SGD
	COMBINATION SWITCH, INSTRUMENTS, CENTRE CONSOLE AND NECESSARY ATTACHED PARTS AND TRIMS		
550451)	RENEW INSTRUMENT PANEL (REMOVED)	6.0	25.20
0340	FRONT BUMPER SUPPORT REPAIR	10.0*	42.00
0742	R/F WING REPAIR	15.0*	63.00
1009	FRONT PANEL CPL REPAIR	10.0*	42.00
2351	ROOF REPAIR	60.0*	336.00
Labour Cost			
	Panel / Mechanical Labour	Hrs 20.50 WU 205.0	861.00
Total of Labour			861.00

Paint

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h	WU	Price SGD
	BONNET NEW PART PAINTING		15.0	
	L/F WING REPAIR PAINTING >50%		17.0	
	R/F WING REPAIR PAINTING >50%		17.0	
	ROOF REPAIR PAINTING >50%		62.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	42.83
0741	L/F WING REPAIR PAINTING >50%	16.59
0742	R/F WING REPAIR PAINTING >50%	16.59
2351	ROOF REPAIR PAINTING >50%	112.58
1009	FRONT PANEL CPL SURFACE PAINT	13.70

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			117.0	
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	14.20	142.0	596.40

Material Cost - Paint

	Price SGD
New Part Painting	42.83
Repair Painting	145.76
Surface-/Blend Paint	13.70
Material-constant Metal Preparation	28.60
Total	230.89

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
------	-------------	-------------	-------------	----------------------------	-----------

Code	Description	Part Number	Part Source	Price SGD
0471	BONNET	53301 68020	Original	350.00 ✓
1416	CHECK	56116 22050		0.00
1415	CLIP FASTENING	56115 30100		0.00
0281	FRONT BUMPER	52119 68130A0	Original	250.00 ✓
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS		
2427	L/F DRIP RAIL MLDG	75552 68020	Original	100.00 ✓
0431	MANUFACTURER BADGE	75303 68010	Original	30.00 ✓
0318	R/F BUMPER BRACKET	52115 68040	Original	35.00 ✓
2428	R/F DRIP RAIL MLDG	75551 68020	Original	100.00 ✓
0562	RIGHT HEADLAMP ASSY	81130 68070	Original	420.00 ✓
1408	UPP FRT SCREEN SEAL	56118 68020		0.00
4331	UPP INSTRUMENT PANEL	55302 68900B0	Original	490.00 ?
1401	WINDSCREEN	56101 68060	Original	500.00 ✓
1411	WINDSCREEN REP KIT	KNGKW12		0.00
1412	WINDSCREEN SEAL	56117 68020	Original	50.00 ✓
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				2,325.00
Fixed Sundry Parts Price				100.00
Total				2,425.00

Extras

Code	Description	Price SGD
1000	WINDSCREEN SEALANT	40.00* ✓
1001	FRT NO.PLATE	35.00* ✓
1002	ERP BRACKET	20.00* ✓
Total Extras		95.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	2,325.00	
Total Parts	100.00	2,425.00
Labour Time Base 10 WU/h		
Total 205.0 WU X 42.00 SGD/h		
Total of Labour	861.00	861.00
Total Of Extras		95.00
Paint Work Time Base 10 WU/h		
Labour Cost 142.0 WU X 42.00 SGD/h		
Material Cost	596.40	
Total Paint Including Material	230.89	827.29
Repair Cost Excludes GST		4,208.29
GST (+7.0%)		294.58
Repair Cost Included GST		4,502.87

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
810151A	ADJUST HEADLAMP		3.0	12.60
520011)	R + R FRONT BUMPER		3.0	12.60
520011)	RENEW FRONT BUMPER (REMOVED)		6.0	25.20
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
810051)	R + R RIGHT HEADLAMP		7.0	29.40
530051)	TRANSFER ATTACHED PARTS FROM BONNET		3.0	12.60
530051)	RENEW BONNET		1.0	4.20
	INCLUDES: R + R OR RENEW ATTACHED PARTS			
530111	R + R BONNET LOCK		2.0	8.40
554011	R + R FRONT SCREEN		30.0	126.00
	INCLUDES: TRIM, WIPER ARMS, DRIP RAIL MOULDING, A-PILLAR TRIM, EDGE PROTECTION, SUN VISORS AND INTERIOR MIRROR			
743201	R + R HEADLINING		22.0	92.40
550451)	R + R INSTRUMENT PANEL		7.0	29.40
	INCLUDES: R + R STEERING WHEEL, AIRBAG,			

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 234W

Vehicle Details

Vehicle No.: SLA2910M
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Apr 2022
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 CVT
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 2ZR1720247
Chassis No.: JTDGG20W50J003688
Maximum Power Output: 105.0 kW (140 bhp)
Open Market Value: \$19,953.00
Original Registration Date: 26 Feb 2016
First Registration Date: 26 Feb 2016
Transfer Count: 1
Actual ARF Paid: \$19,953.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Feb 2026
PARF Rebate Amount: \$12,969.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,089.00
COE Rebate Amount: \$19,260.00
Total Rebate Amount: \$32,229.00

The information contained herein is correct as at 21 Apr 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/04/2022 15:42 (SGT)
Date of Accident 14/04/2022 20:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information TOWARDS CHOA CHU KANG DRIVE (BEHIND NORTHVALE CONDO)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLA2910M

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner AMY SPA & FOOT REFLEX
Company Reg No 5XXXX234W
Email Address kwangseng2387@gmail.com
Mobile Phone No (Phone) +65-98592387
Alternative Phone No +65-98592387

VEHICLE PARTICULARS

Manufacturer Toyota
Model WISH 1.8 CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1798


INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00079522100
Cover Note Number 18/04/21 - 25/08/22

DRIVER

Name of Driver BEK KWANG SENG

Sketch Plan Northvale
Condo



A: SLA2910M

B: Bicycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 14/4/22 8:30pm
(Towards Chua Chu Kang Drive)
(Behind Northvale Condo)

Traffic light was green in my direction so I proceed to cross.
A bicycle dashed out from my right & hit my right headlamp
then slide towards my front windscreen. Cyclist was conveyed to
hospital by ambulance. Police send me to Traffic Police to record
statement. * I will submit Police Report to my insurance *
So chaw accept report without vehicle & police report.

**Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
under your own comprehensive policy. Please check with your policy for more information.**

AMY SPAS FOOT REFLEX

BLK 105 YISHUN AVENUE ROAD
#01-163 SINGAPORE 760106
TEL: 6265 8006

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

(YS) 19/4/22
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party (/) Reporting Only
() Claim OD/TP at other workshop ()