



## Service Request Details

Claim

S2M03ZPB

Reference

CS3/ASM22003988/y3 

Loss Date

26 April 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

28 Apr 2022 11:03:37 AM

Request Date

28 April 2022

Due Date

9 May 2022

Services

Pre-Repair Survey

### Actions

---

Next Step

Agree to perform service

Accept Work

## Vehicle Information

---

Incident Vehicle Registration #

SMX5156X

Make

TPVD- Volvo

Model

S60

## Service Address

---

'''

## Primary Contact/Insured

---

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

## Claim Handler

---

OH Vale

vale.oh@axa.com.sg

## Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes



Menu

TYPE



SENT

28/4/22 12:02 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

S2M03ZPB

BODY

Dear Vale, Thank you for the assignment. Please be...

