

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

days

Res.: Yes or No

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$))

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	288K

Vehicle Details

Vehicle No.:	FBN1601L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Apr 2022
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	G3H6E0009654
Chassis No.:	MH3SG431000007455
Maximum Power Output:	-
Open Market Value:	\$2,455.00
Original Registration Date:	25 Jul 2018
First Registration Date:	25 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$369.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	24 Jul 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,889.00
COE Rebate Amount:	\$4,294.00
Total Rebate Amount:	\$4,294.00

The information contained herein is correct as at 29 Apr 2022

OK



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

NO. : 40547

DATE : 16/04/2022
CLAIM NO. : 11922
POLICY NO. : MC/01008801
FROM : RAYMOND

VEHICLE NO : FBN1601L
MAKE/MODEL : YAM / NMAX155 ABS

Not Available
2/5
4 days
29/4/22
To be photo attached

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	Cur 35.00
2	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	Cur 55.00
3	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00	Cur 222.00
4	BRACKET MASTER CYLINDER RH P/N: 60166 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	Cur 10.00
5	COVER SIDE LOWER RH (WHITE) P/N: 58117 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	Cur 22.00
6	COVER SIDE RH (SILVER) P/N: 60879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	Cur 38.00
7	COWLING FRONT RH (WHITE) P/N: 59594 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	Cur 35.00
8	DAMPER PLATE P/N: 64847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	Dis 30.00
9	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	Cur 15.00

*40547 *

bisafe



S/N	Description	Action	Qty	Unit Price	Amount
10	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00
11	GASKET EXHAUST PIPE P/N: 58162 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
12	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	4.00	\$63.00	252.00
13	LEVER BRAKE RH P/N: 58185 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
14	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
15	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$52.00	52.00
16	PANEL 2 (GREY) RH P/N: 58081 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
17	PIPE EXHAUST ASSY P/N: 58083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$407.00	407.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
19	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
20	REFLECTOR ASSY REAR P/N: 63813 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	15.00
21	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	6.00
22	SPRAY LACQUER ON COVER SIDE RH - (REPORTED BY MECHANIC)	Spray	1.00	\$90.00	90.00
23	SPRAY LACQUER ON COWLING FRONT RH - (REPORTED BY MECHANIC)	Spray	1.00	\$90.00	90.00
24	STICKER (CISCO) COVER CENTRE RH P/N: 58615 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00

*40547 *



S/N	Description	Action	Qty	Unit Price	Amount
25	STICKER (CISCO) COWLING FRONT RH P/N: 58617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
26	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$40.00	40.00
SUB TOTAL					\$1,716.00
GST @ 7 %					\$120.12
GRAND TOTAL (SGD)					\$1,836.12

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Auto-Gen signature hence notify the Receiver of the following:

- Commodity bill of lading or shipping
- Truck Receipt and delivery receipt
- For items, no receipt to confirmation
- Third party liability (Third Party Liability) basis
- Delivery and receipt of goods
- Supplementary terms must be provided and

Acknowledged by Receiver

Signature

Date

*40547 *

