

Enquire Vehicle's Insurance Particulars (As At 09 Dec 2021 / 14:28:00)

Vehicle No.:

SHA1342G

Make Description/Model:

HYUNDAI / AE IONIQ HEV FL 1.6 DCT

Insurance Company Name:

AXA INSURANCE PTE LTD

Business Transaction Reference No.:

20211209163621399813

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).



Thank you

Kwok Bonnie has successfully logged out.

Your last login date and time was 09 Dec 2021, 16:35:25.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
1	Vehicle	SHA1342G	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 10/12/2021

Your Ref No: EngSoon-SLG6770S

Dear Sir/Madam,

Date of Accident: 09/12/2021 00:00 (SGT)

Vehicle No: SLG6770S

Place of Accident: BKE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA1342G	BKE, Singapore	(29.00)	1	(27.10)
GST Amount				(1.90)
Total Amount Due (GST Inclusive)				(29.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/12/2021 19:03 (SGT)
Date of Accident	09/12/2021 14:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BKE TOWARDS WOODLANDS BEFORE WOODLANDS AVENUE 3 EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG6770S
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MOHD AZIZ BIN MOHD SALLEH
NRIC No	S1291409A
Email Address	MOHDAZIZBMS@GMAIL.COM
Mobile Phone No	(Phone) +65-98155033
Alternative Phone No	+65-98155033

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5104017571-03
Cover Note Number	-

DRIVER

Name of Driver	MOHD AZIZ BIN MOHD SALLEH
----------------------	---------------------------

NRIC No	S1291409A
Date Of Birth	18/08/1958
Occupation	Indoor
Date Of Driving Pass	07/06/1994
Driving experience	27 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98155033
Alt. Phone Number	+65-98155033
Email Address	MOHDAZIBMS@GMAIL.COM
Address	BLK 793 WOODLANDS AVENUE 6 #02-667
Address complement	-
Postcode	730793
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ON THE LEFT LANE AT THE SAID LOCATION TO EXIT ONTO WOODLANDS AVENUE 3 WHEN SUDDENLY A TAXI COLLIDED ONTO MY REAR RIGHT PORTION. SUBSEQUENTLY THE TAXI LOST CONTROL & HIT ONTO MY FRONT RIGHT PORTION FOR THE 2ND TIME. WE THEN STOP BY THE ROADSIDE AND TOOK PHOTOS & EXCHANGE PARTICULARS.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA1342G
Vehicle Manufacturer	Hyundai
Vehicle Model	Ioniq
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Taxi
Name of Driver	A ISKANDAR BIN ALAWI

NRIC No	S6826947D
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 09/12/2021

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: GADDAFI

NRIC/FIN No.: S993841

























SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/12/2021 10:29 (SGT)
Date of Accident 09/12/2021 14:30 (SGT)
Exact Location of Accident BKE, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA1342G

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

VEHICLE PARTICULARS

Manufacturer Hyundai
Model Ae ioniq
Variant -
Vehicle Category Taxi
Transmission Auto
CC 1580

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage ThirdPartyFireTheft
Fleet Policy Yes
Policy Number VFX/P2419138
Cover Note Number -

DRIVER

Name of Driver A ISKANDAR BIN ALAWI
NRIC No S6826947D
Address 810 WOODLANDS STREET 81 #04-191
Address complement -
Postcode 730810
Does Driver Own Other Vehicles? No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
Weather Conditions Clear

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Was anybody injured in the Accident? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1

CIRCUMSTANCES OF ACCIDENT

ON THE 09/12/21 AT ABOUT 1430HRS WHILE DRIVING MY VEHICLE SHA1342G, VEHICLE A ALONG BKE TOWARDS WOODLANDS CHECKPOINT BEFORE WOODLANDS AVE 3 EXIT, AS I WAS CHANGING LANE, I WAS UNABLE TO STOP IN TIME TO AVOID VEHICLE SLG6770S, VEHICLE B. RESULTING IN A SIDE SWIPE COLLISION. PARTICULARS EXCHANGED NO INJURIES AT THE TIME OF ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes
Reasons for not uploading a video of the accident FILE IS NOT SUITABLE
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG6770S
Vehicle Manufacturer Toyota
Vehicle Model Camry
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver MOHD AZIZ BIN MOHD SALLEH
Insurance Company Name -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON THE 09/12/21 AT ABOUT 1430HRS WHILE DRIVING MY VEHICLE SHA1342G, VEHICLE A

ALONG BKE TOWARDS WOODLANDS CHECKPOINT BEFORE WOODLANDS AVE 3 EXIT, AS I WAS CHANGING LANE, I WAS UNABLE TO STOP IN TIME TO AVOID VEHICLE SLG6770S, VEHICLE B. RESULTING IN A SIDE SWIPE COLLISION.

PARTICULARS EXCHANGED
NO INJURIES AT THE TIME OF ACCIDENT

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel







































AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Mohd Aziz Bin Mohd Salleh
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP21120022
Date: 31 MAR 2022

Vehicle no: SLG6770S

Model : TOYOTA CAMRY 2.0

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 10 DEC 2021 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 850.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 850.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP21120022

Date: 31 MAR 2022

Mohd Aziz Bin Mohd Salleh
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY ACCIDENT OCCURED ON 09 DEC 2021

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 10 DEC 2021
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SLG6770S

1. VEHICLE PARTICULARS

Registration No : SLG6770S
Model : TOYOTA CAMRY 2.0
Year / Capacity : Sep 2008 / 1998 cc
Chassis No : MR053BK4107034438

Engine No : 1AZE114207
Mileage : N.A km
Colour : Metallic Black

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLG6770S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front bumper	bent	\$ 650.00	\$ 650.00
1 pc	Front bumper side retainer	bent	\$ 65.00	\$ 65.00
1 pc	Front bumper reinforcement	bent	\$ 350.00	\$ 350.00
10 pcs	Front bumper clips	necessary	\$ 80.00	\$ 80.00
1 pc	Headlamp assembly	grazed/deformed	\$ 845.00	\$ 845.00
1 pc	Headlamp clips	necessary	\$ 15.00	\$ 15.00
1 pc	Front fender	bent	\$ 525.00	\$ 525.00
1 pc	Front fender splash shield	deformed	\$ 150.40	\$ 150.40
10 pcs	Front fender splash shield clips	necessary	\$ 80.00	\$ 80.00
1 pc	Front door assembly	bent	\$ 1,050.00	\$ 1,050.00
1 pc	Front door weatherstrip	bent	\$ 165.00	\$ 165.00
1 pc	Front door outer protector	grazed/deformed	\$ 115.00	\$ 115.00
8 pcs	Front door outer protector clips	necessary	\$ 80.00	\$ 80.00
1 pc	Front knuckle arm	bent	\$ 381.50	\$ 381.50
1 pc	Front lower arm	bent	\$ 120.50	\$ 120.50
1 pc	Front absorber	bent	\$ 425.00	\$ 425.00
1 pc	Front wheel bearing hup	bent	\$ 180.50	\$ 180.50
1 pc	Front link rod assy	distorted	\$ 88.90	\$ 88.90
1 pc	Rear door assembly	bent	\$ 1,250.00	\$ 1,250.00
1 pc	Rear door outer protector	grazed/deformed	\$ 105.00	\$ 105.00
8 pcs	Rear door outer protector clips	necessary	\$ 64.00	\$ 64.00
1 pc	Rear door weatherstrip	bent	\$ 150.00	\$ 150.00
1 pc	Rocker panel garnish	deformed	\$ 450.00	\$ 450.00
10 pcs	Rocker panel garnish clips	necessary	\$ 80.00	\$ 80.00
1 pc	Rear lower arm	bent	\$ 250.00	\$ 250.00
1 pc	Rear upper arm	bent	\$ 280.00	\$ 280.00
1 pc	Rear control arm	bent/distorted	\$ 180.00	\$ 180.00
1 pc	Rear cross member	bent/distorted	\$ 750.00	\$ 750.00
1 pc	Rear wheel bearing hup	distorted	\$ 125.00	\$ 125.00
1 pc	Rear anti roll bar link	bent/distorted	\$ 80.00	\$ 80.00
1 pc	Rear shock absorber	distorted	\$ 220.00	\$ 220.00
1 pc	Side mirror housing assy	grazed/deformed	\$ 579.80	\$ 579.80

Vehicle Number : SLG6770S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Rear fender	bend/distorted	\$ 725.00	\$ 725.00
1 pc	Rear bumper	bent	\$ 650.00	\$ 650.00
1 pc	Rear bumper side retainer	bent	\$ 50.00	\$ 50.00
1 pc	Rear bumper side bracket	bent	\$ 65.00	\$ 65.00
1 pc	Rear bumper lower bracket	bent	\$ 85.00	\$ 85.00
10 pcs	Rear bumper clips	necessary	\$ 80.00	\$ 80.00
1 pc	Tail lamp assy	distorted	\$ 425.00	\$ 425.00
1 pc	Tail lamp sealant	necessary	\$ 50.00	\$ 50.00
2 pcs	Tail lamp clips	necessary	\$ 40.00	\$ 40.00
1 pc	Tail lamp base panel	dent/distorted	\$ 362.40	\$ 362.40
Parts Sub-Total			\$ 12,463.00	\$ 12,463.00
Discount 25.00%			\$ 3,115.75	\$ 3,115.75
			\$ 9,347.25	\$ 9,347.25

Vehicle Number : SLG6770S

SPARE PARTS


QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 pc	wheel rim assy (sport)	damaged	\$ 600.00	\$ 600.00
1 pc	Tyre	grazed	\$ 450.00	\$ 400.00
Special Nett Sub-Total			\$ 1,050.00	\$ 1,000.00
Spare Parts Total			\$ 13,513.00	\$ 13,463.00

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare Parts Total c/f	\$ 13,513.00	\$ 13,463.00
1	Towing	\$ 120.00	\$ 120.00
2	To check and reconnect snap wiring	\$ 180.00	\$ 150.00
3	To tuff coat affected areas	\$ 180.00	\$ 150.00
4	To remove and transfer front and rear door mechanism	\$ 200.00	\$ 180.00
5	To respray affected areas	\$ 1,600.00	\$ 1,400.00
6	To remove and refix interior upholstery	\$ 180.00	\$ 150.00
7	To renew damaged parts, straighten and repair door center pillar (inner), front door pillar, rear fender, rocker panel and aligned all parts.	\$ 1,800.00	\$ 1,600.00
8	To dismantle/replace all suspension and undercarriage parts.	\$ 280.00	\$ 250.00
9	To press out and in wheel bearing	\$ 180.00	\$ 150.00
10	To conduct wheel alignment.(Before & After)	\$ 180.00	\$ 150.00
	Total	\$ 18,413.00	\$ 17,763.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 14,000.00



Fong Kok Heng
Qualified Appraiser



ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677978
Tel: 6760 6271

Mohd Aziz Bin Mohd Salleh
c/o M/s Eng Soon Painting Services
Block 4 Yew Tee Ind Est 393-
Woodlands Road
Singapore 677969

Date: 31 March 2022

Dear Sir,

Date of accident : 09/12/2021
Final repair bill to: SLG 6770 S

To Supply,

Repairs recommended By the surveyor	14,000.00
Total	\$14,000.00

Dollars: FOURTEEN THOUSAND ONLY



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
ROAD TRANSPORT (AMENDMENT) ACT, 2019 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5104017571-03 Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : SLG67705
Chassis Number : MR053BK4107034438

2. Name of Policyholder : MOHD AZIZ BIN MOHD SALLEH

3. Effective Date of Insurance : 24 Sep 2021

4. Expiry Date of Insurance : 23 Sep 2022

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Policy, the Schedule, En... read together as one document.