



Your Ref: S1M03NZ8

Date: 26th May 2022

Our Ref: CS3/ASM21012516/Gvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLG 6770S
INSURED VEHICLE: SHA 1342G
ACCIDENT DATE: 09/12/2021**

We thank you for your instruction on 29/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLG 6770S from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles SLG 6770S and SHA 1342G.
- c) Final Repair Bill of SLG 6770S from M/s Eng Soon Painting Services.
- d) Colour damaged vehicle photographs of SLG 6770S.

Pre-Repair Inspection Date : 10/12/2021 at M/s Eng Soon Painting Services, Blk 4 Yew Tee Ind Est 393-J Woodlands Road, Singapore 677969.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|------------------------------------|
| Registration Number | : SLG 6770S |
| Make & Model | : Toyota Camry 2.0 Auto ABS Airbag |
| Year of Registration | : 2008 |
| Chassis Number | : MR053BK4107034438 |
| Engine Capacity | : 1998 cc |

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.