

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

Date: 28.04.2022

Time: 09:47:42

Page: 1

T3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305514148
 REGN NO : SHC1154Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 12.07.2018
 DATE/TIME IN : 28.04.2022 08:10
 ACCIDENT DATE : 28.04.2022

NTUC-CP(P)

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2537-G WING MIRROR LH

1 1,391.70 20.00 1,113.36 bvo ✓

SUB-TOTAL : 1,113.36 ✓

JOB NATURE

0000 PB PANEL BEATING-SHC1154Y-TP

150.00 ✓

0001 SP SPRAYPAINT CHARGE

150.00 100

0002 17-01 CHECK WIRING.

40.00 30 280

SUB-TOTAL : 340.00

Wings

TOTAL : 1,453.36 1393.36

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Tanjong 97495749
 esp' 28/4/22 @ 4:00pm
 L/S Resurvey after repair
 01 day
 tanjoh e lkhantow

1/58/1100
 01 day
 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: