



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205503

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 07/09/2022  
Reference CC3/CTI22004049/Tea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SH 8932R  
Insured Veh. CB 6452T  
Claim No. SNM22D202896/C02  
Policy No. DMB1SNW00014052100  
Accident Date 28/04/2022  
Inspection Date 28/04/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                          |                 |                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|-----------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                          |                 | Ref: CC3/CTI22004049/Tea3q2 |  |
|                                                                                                                                        |                                                                          |                 | Date: 07/09/2022            |  |
|                                                                                                                                        |                                                                          |                 | Code: CTI                   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |                 |                             |  |
| Insured Veh.                                                                                                                           | CB 6452T                                                                 | Veh. Inspected  | SH 8932R                    |  |
| Policy No.                                                                                                                             | DMB1SNW00014052100                                                       | Coverage (\$)   | 0.00                        |  |
| Claim No.                                                                                                                              | SNM22D202896/C02                                                         | Excess (\$)     | 0.00                        |  |
| Assign From                                                                                                                            |                                                                          | Assign Date     | 28/04/2022                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |                 |                             |  |
| Make & Model                                                                                                                           | TOYOTA PRIUS                                                             | c.c             | 1798                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.    | 2017                        |  |
| Chassis No.                                                                                                                            | JTDKB3FU303564383                                                        | Colour          | BLUE                        |  |
| Odometer                                                                                                                               | 492820 KM                                                                | Steering        | IN ORDER                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                 | Modification    | NIL                         |  |
| General                                                                                                                                | GOOD                                                                     |                 |                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |                 |                             |  |
|                                                                                                                                        | Size                                                                     | Make            | Balance                     |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                               | WEST LAKE       | 6 mm                        |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                               | WEST LAKE       | 6 mm                        |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | WEST LAKE       | 6 mm                        |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | WEST LAKE       | 6 mm                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.                                                                 |                                                                          |                 |                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                          |                 |                             |  |
| Accident Date                                                                                                                          | 28/04/2022                                                               | Inspection Date | 28/04/2022                  |  |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          |                 | <b>1 Working Days</b>       |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8932R

| Qty | Description of Parts                                                            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                              |               |                           |                   |
| 1   | WING MIRROR LH                                                                  | BROKEN        | 1,390.10                  | 1,390.10          |
| 1   | WING MIRROR OTR CVR LH                                                          | MISSING       | 141.90                    | 141.90            |
| 1   | FRT DOOR GLASS LH                                                               | CUT           | 313.60                    | 313.60            |
| 1   | FRT DR OUTER MOULDING LH                                                        | NOT NECESSARY | 188.60                    | -                 |
|     | LESS 25% DISCOUNT                                                               |               | -508.55                   | -461.40           |
|     |                                                                                 |               | 1,525.65                  | 1,384.20          |
|     | <b><u>LABOUR</u></b>                                                            |               |                           |                   |
|     | PANEL BEATING.                                                                  |               | 300.00                    | 175.00            |
|     | SPRAYPAINT CHARGE.                                                              |               | 150.00                    | 100.00            |
|     | CHECK WIRING.                                                                   |               | 40.00                     | 30.00             |
|     |                                                                                 |               | 490.00                    | 305.00            |
|     | <b>GRAND TOTAL</b>                                                              |               | <b>2,015.65</b>           | <b>1,689.20</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |               |                           | <b>1,350.00</b>   |

Report Ref No. CC3/CTI22004049/Tea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SH 8932R

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SH 8932R

### RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

