

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	UNITED OVERSEA	LOTION INE	Ref:	CS3/UOI22004061/Vvy3e2		
	146 ROBINSON RO		Date:	27/05/2022		
	SINGAPORE 0689		Date.	21700/2022		
				Code:	UOI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLR 9750Y	Veh. Inspected	t	SJV 3308J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	M11D15112205	Excess (\$)		0.00	
	Assign From	JOSEPHINE WONG	Assign Date		29/04/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ B180	c.c		1332	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	W1K2470842J120695	Colour		SILVER	
	Odometer	12977 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
	I	Size	Make		Balance	
	R/H Front Tyre	225/45 R18	BRIDGESTONE		6 mm	
	L/H Front Tyre	225/45 R18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	225/45 R18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	225/45 R18	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	General Information					
	Accident Date	29/04/2022	Inspect Date /	Time	29/04/2022 (01:00 PM)	
	Survey held at	Survey held at GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875				
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/UOI22004061/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser