

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC22004068/7	「qcn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	31-05-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YQ 2398D	Veh. lı	nspected	SHB 6365C	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1170574-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	29/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2020	
	Chassis No.	KMHC851CVLU190078	Colou	r	BLUE	
	Odometer	338014	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/04/2022		tion Date	29/04/2022	
	Survey held at	eld at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	c. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					