

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NAUC (P/P)

Date: 29.04.2022 Jumar:

Time: 14:56:10

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305514216
 REGN NO : SHB6365C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 18.03.2020
 DATE/TIME IN : 29.04.2022 10:15
 ACCIDENT DATE : 28.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	COVER-FR BUMPER#	1	481.10	0.00	481.10	Ry	
0002 04-01-0104-2835-G	LAMP ASSY-HEAD LH#	1	2,110.30	0.00	2,110.30	cre	
0003 04-01-0104-0600-G	DEP MIRROR ASSY-OUTSIDE R	1	1,391.70	0.00	1,391.70	hno	
0004 04-01-0104-0574-G	PANEL-FENDER LH#	1	588.80	0.00	588.80	Ry	
0005 04-01-0104-3813-G	EMBLEM-BLUE DRIVE LH	1	26.60	0.00	26.60	aq	
						SUB-TOTAL : 4,598.50	

3528.60

20% 2822.88

JOB NATURE

0000 PB	PANEL BEATING	800.00	525	
0001 SP	SPRAYPAINT CHARGE	700.00	600	
0002 17-01	CHECK ALL LIGHTING	50.00	30	1155
				SUB-TOTAL : 1,550.00

Tanpin 97495749

wp/ 29/4/22 @ 320pm

P/P Resurvey before paint

2 days

tanpin@lkkauto.com

2822.88

1155

\$3977.88

2 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: