

## ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

DAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKH 8368P Yr Regn: 28/12/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo S60 c.c. 1596Colour: White A/C: Insured / Std / Nil / NASp. Reading: 109238 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: YK18548 HISP 7101809

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRM / STD A/Rim or

Tyre Size: F: 215/50R17R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 27/4/22 D.O.I. 4/5/22Survey held at Wah HongDes. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-90K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.S.: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	656Z
<b>Vehicle Details</b>	
Vehicle No.:	SKH8368P
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Apr 2022
Vehicle Make:	VOLVO
Vehicle Model:	S60 T4
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B4164T1114701
Chassis No.:	YV1FS48HBD2201802
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$31,981.00
Original Registration Date:	28 Dec 2012
First Registration Date:	28 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$31,981.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2022
PARF Rebate Amount:	\$15,990.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Feb 2032
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$56,670.00
COE Rebate Amount:	\$55,741.00
<b>Total Rebate Amount:</b>	<b>\$71,731.00</b>

The information contained herein is correct as at 28 Apr 2022

OK





# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC398				Page No. 1	
Vehicle No. : SKH8368P					
Make & Model : VOLVO S60 T4					
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT	
<b>PARTS (LIST ITEMS)</b>					
1	Side mirror RH ✓ <i>OR</i>		2342.00		
1	Front Door RH (Repair refer to labor)		0.00		
1	Rear Door RH (Repair refer to labor)		0.00		
1	Rear fender RH(Repair refer to labor)		0.00		
			<b>Part Items Total:</b>	<b>2342.00</b>	
			<b>-10%</b>	<b>-234.20</b>	
			<b>2107.80</b>		
<b>SPECIAL NETT ITEMS</b>					
<b>SN Items Total:</b>			<b>0.00</b>		
<b>Total Parts:</b>			<b>2107.80</b>		

*Steve (LKK)*  
*4/5/22, 11.00am*

*mm RL*  
*P/P*  
*My RL*  
*4 Lys*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 2

Our Ref	: UC398
Vehicle No.	: SKH8368P
Make & Model	: VOLVO S60 T4

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	<b>LABOUR</b> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	410
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	900
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
Labour Total :		1920.00	
TOTAL (PARTS & LABOUR):		4027.80	



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	28/04/2022 15:52 (SGT)
Date of Accident	27/04/2022 18:23 (SGT)
Exact Location of Accident	Near Bukit Batok Rd, Singapore
Additional Location Information	BUKIT BATOK RD TOWARDS JURONG TOWN HALL RD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH8368P
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	FOONG YIEW MING
NRIC No	SXXXX656Z
Email Address	YIEWMING@GMAIL.COM
Mobile Phone No	(Phone) +65-98418966
Alternative Phone No	+65-98418966

### VEHICLE PARTICULARS

Manufacturer	Volvo
Model	S60
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1596

### INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2021-V8010645-VDP-R001
Cover Note Number	-

### DRIVER

Name of Driver	FOONG YIEW MING
NRIC No	SXXXX656Z

Date Of Birth 04/10/1964  
 Occupation Indoor  
 Date Of Driving Pass 07/02/1987  
 Driving experience 35 YEARS AND 2 MONTHS  
 Gender Male  
 Mobile Number (Phone) +65-98418966  
 Alt. Phone Number +65-98418966  
 Email Address YIEWMING@GMAIL.COM  
 Address 53 JURONG EAST AVE 1  
 Address complement #09-02  
 Postcode 609783  
 Is the driver the policyholder? Yes  
 If No, Relationship of the Driver with the Insured -  
 Does Driver Own Other Vehicles? No  
 Vehicle Registration Number of Other Vehicle Owned by Driver -  
 Insurance Company of Other Vehicle Owned by Driver -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe  
 Weather Conditions Clear  
 Road Surface Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
 Number of vehicles involved in the accident 2  
 Was anybody injured in the Accident? No  
 Was any injured conveyed to hospital by ambulance? -  
 Was any other vehicle or property damaged? Yes  
 Number of Passengers (Including Driver) 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes  
 Police Station Name Jurong East Neighbourhood Police Centre  
 Police Station Phone No (Phone) +65-18008999999  
 Alt. Police Station Phone No (Fax) +65-66655791  
 Police Station Address No. 92 Boon Lay Way Singapore 609962  
 Was notice of intended Prosecution given? No  
 If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? Yes  
 Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE4321L  
 Vehicle Manufacturer -  
 Vehicle Model -  
 Vehicle Variant -  
 Vehicle Colour -  
 Vehicle Category Commercial vehicle





Name of Driver	CHUA KOON SAN
Contact Number	(Phone) +65-81802990
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan





**Describe Circumstances of the Accident**


On 27 Apr. 2022 at about 1823 I was driving my vehicle A (SKH 8368P) along Putit Batak Road towards Judding Town Hall Road. Suddenly, a vehicle B (XE 4321L) swerve towards my right side of my car. I was driving on left most lane. He was driving on my right lane behind me. Therefore, vehicle B hit my car.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
 Witnessed by Reporting Centre Personnel



## NOTICE OF REPORTING

This is to confirm that Foong Yiew Ming, NRIC/FIN

S2568656Z, has reported to the Police a non-injury traffic accident which

occurred along Bt Batok Rd towards Jurong Town Hall Rd,

on 27/04/2022 at 06:23 am/pm involving the following vehicles:

SKH 8368 P

Volvo

S60

White

XE 4321 L

Isuzu

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt(3) Ngu Yuan Jin

Date: 27/04/2022 Time: 2100hrs

S/D Ref: 102

Police Post/Unit : Jurong East NPC

Original - to be issued to informant

Duplicate - to be submitted to Traffic Police

Jurong East  
Neighbourhood Police Centre  
No 92 Boon Lay Way  
Singapore 609962  
Tel : 1800-8999999