

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/05/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5759A
Case Reference Number	BUS/04/22/7019
Registration Date	18/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Juraimi Hairul Nizam Bin Kamsan
Type of Accident	Head To Side
Accident Date and Time	19/4/2022 7:02 AM
Accident Reported Date and Time	28/4/2022 8:55 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114790
Special Instruction to ARC,if any	SG5759A - Left side body scratched and dented. SMT7058D (TP) - INSURED WITH
Prepared Date and Time	28/4/2022 10:47 AM
Chassis Number	WMAA95ZZ5G7003215
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$956.00	\$616.00
Total Spare Part Cost	\$2,251.74	\$2,251.74
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,327.74	\$4,457.74
Lump Sum Total	\$5,350.00	\$4,450.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kok Khoon Goh	GuoQiang
ARC / Surveyor Sign Off Date	28/04/2022 11:01 AM	29/04/2022 12:36 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/05/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				\$1,590.00 ✓		
Total Labour			\$2,120.00				\$1,590.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$956.00				\$616.00 ✓		
Total Spray Painting & Panel Beating			\$956.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013447	BODY RH	155-2-2-001-006	SIDE PANEL R6 CRA	1.00	\$467.50	10.00	\$420.75 ✓	Replace	Replace
6013446	BODY RH	155-2-2-001-005	SIDE PANEL R5 CRA	1.00	\$1,192.50	10.00	\$1,073.25 ✓	Replace	Replace
6010330			WHEEL ARCH TRIM Mis	1.00	\$124.20	10.00	\$111.78 ✓	Replace	Replace
	DOOR		DOOR COCK (ASSEMBLY) Cut	1.00	\$625.00	10.00	\$562.50 ✓	Replace	Replace
	Body		RUBBER DOOR PILLAR FRONT Tn	1.00	\$306.00	10.00	\$275.40 ✓	Replace	Replace
			STICKER SMRT Nec	1.00	\$75.00	0.00	\$75.00 ✓	Replace	Replace
4006314			SEALANT SIKAFLEX Nec	8.00	\$37.00	0.00	\$296.00 ✓	Replace	Replace
Total					\$2,827.20		\$2,814.68		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									