



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|--------------------------|------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 | | | Ref: CS/ASM22004082/Aty3 | |
| | | | Date: 04/05/2022 | |
| | | | Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHB 4111G | Veh. Inspected | PC 7592G |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | S2M03ZWS | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 04/05/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| | Accident Date | 28/04/2022 | Inspection Date | 04/05/2022 |
| | Survey held at | UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |