



Your Ref: 22.29651

Date: 02nd Jun 2022

Our Ref: CS3/ASM21005480/Tvy3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP
36 Robinson Road #12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 9888X
INSURED VEHICLE: SHB 7950G
ACCIDENT DATE: 03/05/2021**

We thank you for your instruction on 27/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 9888X from M/s Automax Survey.
- b) Singapore Accident Statement and Police Report of Vehicles SMD 9888X and SHB 7950G.
- c) Final Repair Bill of SMD 9888X from M/s D's Graffiti Concepts Pte Ltd.
- d) Colour damaged vehicle photographs of SMD 9888X.

Pre-Repair Inspection Date : 05/05/2021 at M/s Merlin Motor & Engineering Works, Blk 10 Ang Mo Kio Industrial Park 2A #03-13 AMK Autopoint, Singapore 568047.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMD 9888X
Make & Model	: Honda Vezel Hybrid 1.5X A
Year of Registration	: 2016
Chassis Number	: RU31214933
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.