


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 7.5k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBL18720 Yr Regn: 117/116  
 Type: M.Car / M.Cycle Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda CBF190WH c.c 184  
 Colour: black A/C: Insured / Std / NI / NA  
 Sp. Reading: Not avail T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: LWBMC4692H1101896  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 140/70-17  
 R: 140/70-17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /  
 TOYO / YOKO or  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. \_\_\_\_\_ mm  
 D.O.A. 29/4/22 D.O.I. 5/5/22 1300  
 Survey held at U maps motor  
 Des. of Damages: Frt / Rear O/S N/S U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 7.5k  
rebate: 2582  
NU: 4918  
rr: 1.5k-2k

submit prs report

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

133J

### Vehicle Details

Vehicle No.:

FBL1872G

Vehicle to be Exported:

No

Intended Deregistration Date:

25 May 2022

Vehicle Make:

HONDA

Vehicle Model:

CBF190WH

Primary Colour:

Black

Manufacturing Year:

2016

Engine No.:

MC46E5010625

Chassis No.:

LWBMC4692H1101896

Maximum Power Output:

-

Open Market Value:

\$2,964.00

Original Registration Date:

01 Jul 2016

First Registration Date:

01 Jul 2016

Transfer Count:

3

Actual ARF Paid:

\$445.00

### Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

### Intended COE Rebate Details

COE Expiry Date:

30 Jun 2026

COE Category:

D - Motorcycle

COE Period(Years):

10

QP Paid:

\$6,303.00

COE Rebate Amount:

\$2,582.00

Total Rebate Amount:

\$2,582.00

The information contained herein is correct as at 25 May 2022

OK

$$\begin{aligned} & \text{dp: 150} \\ & 4 \text{ yrs } 2 \text{ / } 50 \\ & 150 \times 50 = 7500 \\ & 7500 - 2582 \\ & = 4918 \end{aligned}$$

Back to results

Honda CBF 190WH AKA CBF 190 WH 2017

12 photos



HONDA CBF190WH AKA CBF 190 WH 2017

S\$9,000

📍 Used

👥 Meetup

📍 Singapore



lim ming sheng @mr\_ms

13 ★★★★★ (100%)

12 items for sale

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold

12 items sold