

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GS1 Reg. No. 19-900/196-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22004136/Utcn2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 23/05/2022	
			Cod	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 3265S	Veh. Inspected	SJP 6612S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015025/CD	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	04/05/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JM6BN22A8K0250676	Colour	BLUE	
	Odometer	45389 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/04/2022	Inspection Date	04/05/2022	
	Survey held at	TAN LIM MOTOR PTE LTD			
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: