

(05/11/03)

ASS. REC. BY: ThavanREF: CS/LPC22004137/VLC Vnc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 131

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FX3022UYr Regn: 17/10/03

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Harley Davidson XL1200C c.c. 1199Colour: blue

A/C: Insured / Std / NI / NA

Sp. Reading: Not avail

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SHD1C6P143K434764Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100 80 16R: 100 80 16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Shinjo

Front

R/Bal. 7 mm

L/Bal. _____ mm

D.O.A. 27/4/22

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 13hredate: 470NV: 12530

30/08/22 SUBMIT PRS REPORT

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

090D

Vehicle Details

Vehicle No.:

FX3022U

Vehicle to be Exported:

No

Intended Deregistration Date:

25 May 2022

Vehicle Make:

HARLEY DAVIDSON

Vehicle Model:

XL1200C

Primary Colour:

Blue

Manufacturing Year:

2003

Engine No.:

CGP3434764

Chassis No.:

5HD1CGP143K434764

Maximum Power Output:

-

Open Market Value:

\$12,612.00

Original Registration Date:

17 Oct 2003

First Registration Date:

17 Oct 2003

Transfer Count:

3

Actual ARF Paid:

\$1,892.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

16 Oct 2023

COE Category:

D - Motorcycle

COE Period(Years):

10

PQP Paid:

\$1,700.00

COE Rebate Amount:

\$470.00

Total Rebate Amount:

\$470.00

The information contained herein is correct as at 25 May 2022

1/15 9/21

dp: 700

700 x 18

= 1260

= 13k

13k - 470

= 12530

OK


dp: 111
~~1/15 6/18~~
~~111 x 18~~
= 1998

Registration Date	18/03/2013
COE Expiry Date	17/03/2023 (9mths 20days COE left)
Mileage	19300km
No. of owners	3
Type of Vehicle	Cruiser

SGD \$12000

Well Maintained Rare Head Turner Harley-davidson Sportster XL1200CA Custom Limited.
In Excellent Condition.
Bike Is Fully Loaded With All Original Harley-davidson Accessories.
Recently Fully Serviced.
Close ^

Similar Bikes

[View More](#)

03/04/2022


Used Bike

★ Direct Seller
Harley Davidson XLB...
Direct Owner Sale. Pristine

\$25000



7



04/04/2022

Used Bike

★ Direct Seller
Harley Davidson Fat...
2016 Model Harley Davidson Fa...

\$35000



1

https://www.carousell.sg/p/harley-sportster-xl1200r-2004-carburetor-model-1155954811/?t-id=Fnl_e_WBuG9_1653445407733&t-referrer_browse_t... 1/2