

ASS. REC. BY: Stere

CS/CT122004150/EVC

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
XXX	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBH 2168X Yr Regn: 19/3/18Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Caddy c.c. 1968Colour: White A/C: Insured / Std / NI / NASp. Reading: 28882 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV1ZZZ2K1X157337Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 29/11/22 D.O.I. 6/5/22Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MR-56X

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.F. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

217 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
3-D
PHOTOGRAPHY
562 ANG MO KIO AVENUE 3
#04-3491
Singapore 560562

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

05-05-2022
5211001170
200208384E
30001
2022012808/ 1
04-05-2022
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
2K0827092G	Wing Door With Window Ope REAR BOOT LID (RH)	1	pcs.	2,769.42	#1	2,769.42	2,963.28
D 169300M2	1k Window Adhesive	1	pcs.	51.44	#1	51.44	55.04
D 00940104	All Purpose Cleaner	1	pcs.	102.88	#1	102.88	110.08
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
D 00950025	Applicator	2	pcs.	11.16	#1	22.32	23.88
WHT007341	Rivetted Cap Nut	2	pcs.	2.64	#1	5.28	5.65
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	#1	43.65	46.71
2K0827091J	BOOT LID INSULATION Wing Door With Window Ope REAR BOOT LID (LH)	1	pcs.	2,769.42	#1	2,769.42	2,963.28
D 169300M2	1k Window Adhesive	1	pcs.	51.44	#1	51.44	55.04
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
N 10580601	Rivetted Cap Nut	4	pcs.	4.83	#1	19.32	20.67
7E0853630D DPJ	Vw Sign Black/Bright Chro	1	pcs.	100.86	#1	100.86	107.92
2K5853687 739	Inscription Chrome NAME PLATE - CADDY	1	pcs.	71.57	#1	71.57	76.58
2K0827709E	Door Seal BOT LID SEAL (CTR)	1	pcs.	77.81	#1	77.81	83.26
7F0945105	Fluorescent Strip BOOT LID REFLECTOR (STICKER)	2	pcs.	35.09	#1	70.18	75.09
2K5827505F	Hood Lock With Micro Swit LHS BOOT LID LOCK (LOWER)	1	pcs.	99.02	#1	99.02	105.95
2K5827506	Hood Latch RHS BOOT LID LOCK (LOWER)	1	pcs.	96.89	#1	96.89	103.67
N 90825401	Rivetted Cap Nut	2	pcs.	2.64	#1	5.28	5.65
D 378500A2	Alu-Lamin. Insulation BOOT LID INSULATION	1	pcs.	43.65	#1	43.65	46.71
2K5807417B 9B9	Cover For Bumper Satin Bl REAR BUMPER	1	pcs.	791.24	#1	791.24	846.63
2K5807441 9B9	Cap Satin Black TOWING COVER	1	pcs.	52.01	#1	52.01	55.65
2K5807305	Bumper REINFORCEMENT	1	pcs.	650.26	#1	650.26	695.78
2K5807393B	Guide Piece BUMPER SIDE BRACKET (LH)	1	pcs.	30.96	#1	30.96	33.13
2K5807394B	Guide Piece BUMPER SIDE BRACKET (SIDE)	1	pcs.	30.96	#1	30.96	33.13
357853586B	Grommet	10	pcs.	1.70	#1	17.00	18.19
N 0385501	Rivet	10	pcs.	0.57	#1	5.70	6.10



Quotation
 Non binding - Preview

Page 2/3

Document no.
 Document date 05-05-2022
 Customer no. 5211001170
 Customer GST-ID 200208384E
 Dealer 30001
 Job order number 2022012808/ 1
 Job order date 04-05-2022
 Service Advisor CHARMAINE KONG

Company
 CHINA TAIPING INSURANCE (S) PL
 3 ANSON ROAD
 #18-00 SPRINGLEAF TOWER
 Singapore 079909

Customer Details:
 Company
 3-D
 PHOTOGRAPHY
 562 ANG MO KIO AVENUE 3
 #04-3491
 Singapore 560562

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
2K5945106D	Reflector	1	pcs.	68.91	#1	68.91	73.73
	RHS REFLECTOR						
2K0813307	Rear Apron	1	pcs.	299.03	#1	299.03	319.96
	REAR END PANEL						
D 007500A2	Zinc Spray	1	pcs.	72.86	#1	72.86	77.96
D 180003M2	2k-Body Adhesive	1	pcs.	469.52	#1	469.52	502.39
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	66.78	#1	66.78	71.45
2K0863459H 82V	Cover For Lock Carrier Ti	1	pcs.	174.76	#1	174.76	186.99
	END PANEL TRIM COVER						
2K0863905 82V	Cap Titanium Black	4	pcs.	3.04	#1	12.16	13.01
701864445B	Speed Nut	4	pcs.	2.64	#1	10.56	11.30
2K0810972E	Wheelhouse Protector	1	pcs.	138.15	#1	138.15	147.82
	RHS REAR FENDER LINER						
	LABOUR	162	pcs.	840.00	#1	1680.00	5,392.80
	SPRAY PAINT	52	pcs.	800.00	#1	4,000.00	4,280.00
	R&R LHS REAR BOOT LID GLASS	1	pcs.	840.00	#1	840.00	898.80
	R&R RHS REAR BOOT LID GLASS	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER LHS BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER RHS BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	70 km/h STICKER	1	pcs.	12.00	#1	12.00	12.84
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00

Quotation valid till 11-05-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	22,366.37	7%	1,618.85	23,126.37	24,745.22
Total	760.00	22,366.37		1,618.85	23,126.37	24,745.22

Steve (LKK)
 6/5/22, 11:30am

HL PL
 P/P
 by Bel
 7 djs

Customer
 LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

VISIT OUR WEBSITE: after-sales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) - to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Service Advisor

VW KSWAGEN CENTRE SINGAPORE
Alexandra Road
Singapore 159934
Reg. No.: 199101494Z
ST No.: M200985052



Commercial
Vehicles

Quotation

Non binding - Preview

Page

3/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
3-D
PHOTOGRAPHY
562 ANG MO KIO AVENUE 3
#04-3491
Singapore 560562

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

05-05-2022
5211001170
200208384E
30001
2022012808/ 1
04-05-2022
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

All invoices are denominated in SGD, unless otherwise stated.

CHINA TAIPING
VS
CHINA TAIPING
12808



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/05/2022 12:49 (SGT)
Date of Accident	29/04/2022 16:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE BEFORE AMK AVE 1 EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH2168X

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	PHOTOGRAPHY 3-D
Company Reg No	5XXXX104C
Email Address	chungeeheng@hotmail.com
Mobile Phone No	(Phone) +65-94231973
Alternative Phone No	+65-94231973

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Caddy
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	CHU NGEE HENG
NRIC No	SXXXX568C

Birth	01/09/1973
Location	Indoor
Or Driving Pass	02/08/2001
ing experience	20 YEARS AND 8 MONTHS
nder	Male
Mobile Number	(Phone) +65-94231973
Alt. Phone Number	-
Email Address	chungeeheng@hotmail.com
Address	562 ANG MO KIO AVENUE 3
Address complement	#04-3491
Postcode	560562
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	OWNER OF COMPANY
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK1108E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN BOON KEEM
NRIC No	SXXXX889E
Contact Number	-
Address	-

complement
Company Name
Of Damage
is of property damaged in accident
Of Passenger (Including Driver)


-
-
-
-
1

Describe Circumstances of the Accident

As I was driving along CTE south bound before Ang Mo Kio Ave 1 exit, a trailer slowed down in front of my van. I braked and slowed down too. Then I saw a white car, SMK 1108 E from my rear view mirror approaching fast towards my van and crashed into the rear of my van.

Declaration

We declare the foregoing particulars are true in every respect.


4 May 2022

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

04 MAY 2022

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


4 May 2022
Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
04 MAY 2022

Sketch Plan

