

ASS. REC. BY: Steve

CS/CT122004150/EVC

## ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SMK 1108EPolicy No. DMPCSNW00185202100Claims No. SNM22D203015/C02/LEEPG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
XXX	XXX

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBH 2168X Yr Regn: 19/3/18Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Caddy c.c. 1968Colour: White A/C: Insured / Std / NI / NASp. Reading: 28882 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WV122221K1X157337Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ mm Rear: \_\_\_\_\_ mm

R/Bal. 4 mm L/Bal. 4 mmL/Bal. 4 mm D.O.I. 6/5/22D.O.A. 29/4/22 Volkswagen

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MR-56X

24/5/22 Steve informed final fig \$16,531.50 (Red 6609.64, 28%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 25/5/22-typist

Report Format: MerimenLump Sum / I.B.F. (\$ \$16,531.50)Days Of Repair: 7Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

# VOLKSWAGEN CENTRE SINGAPORE

217 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

1/3

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Company  
3-D  
PHOTOGRAPHY  
562 ANG MO KIO AVENUE 3  
#04-3491  
Singapore 560562

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

05-05-2022  
5211001170  
200208384E  
30001  
2022012808/ 1  
04-05-2022  
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
2K0827092G	Wing Door With Window Ope REAR BOOT LID ( RH )	1	pcs.	2,769.42	#1	2,769.42	2,963.28
D 169300M2	1k Window Adhesive	1	pcs.	51.44	#1	51.44	55.04
D 00940104	All Purpose Cleaner	1	pcs.	102.88	#1	102.88	110.08
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
D 00950025	Applicator	2	pcs.	11.16	#1	22.32	23.88
WHT007341	Rivetted Cap Nut	2	pcs.	2.64	#1	5.28	5.65
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	#1	43.65	46.71
2K0827091J	BOOT LID INSULATION Wing Door With Window Ope REAR BOOT LID ( LH )	1	pcs.	2,769.42	#1	2,769.42	2,963.28
D 169300M2	1k Window Adhesive	1	pcs.	51.44	#1	51.44	55.04
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
N 10580601	Rivetted Cap Nut	4	pcs.	4.83	#1	19.32	20.67
7E0853630D DPJ	Vw Sign Black/Bright Chro	1	pcs.	100.86	#1	100.86	107.92
2K5853687 739	Inscription Chrome NAME PLATE - CADDY	1	pcs.	71.57	#1	71.57	76.58
2K0827709E	Door Seal BOT LID SEAL ( CTR )	1	pcs.	77.81	#1	77.81	83.26
7F0945105	Fluorescent Strip BOOT LID REFLECTOR ( STICKER )	2	pcs.	35.09	#1	70.18	75.09
2K5827505F	Hood Lock With Micro Swit LHS BOOT LID LOCK ( LOWER )	1	pcs.	99.02	#1	99.02	105.95
2K5827506	Hood Latch RHS BOOT LID LOCK ( LOWER )	1	pcs.	96.89	#1	96.89	103.67
N 90825401	Rivetted Cap Nut	2	pcs.	2.64	#1	5.28	5.65
D 378500A2	Alu-Lamin. Insulation BOOT LID INSULATION	1	pcs.	43.65	#1	43.65	46.71
2K5807417B 9B9	Cover For Bumper Satin Bl REAR BUMPER	1	pcs.	791.24	#1	791.24	846.63
2K5807441 9B9	Cap Satin Black TOWING COVER	1	pcs.	52.01	#1	52.01	55.65
2K5807305	Bumper REINFORCEMENT	1	pcs.	650.26	#1	650.26	695.78
2K5807393B	Guide Piece BUMPER SIDE BRACKET ( LH )	1	pcs.	30.96	#1	30.96	33.13
2K5807394B	Guide Piece BUMPER SIDE BRACKET ( SIDE )	1	pcs.	30.96	#1	30.96	33.13
357853586B	Grommet	10	pcs.	1.70	#1	17.00	18.19
N 0385501	Rivet	10	pcs.	0.57	#1	5.70	6.10





**Quotation**  
 Non binding - Preview

Page 2/3

Document no.  
 Document date 05-05-2022  
 Customer no. 5211001170  
 Customer GST-ID 200208384E  
 Dealer 30001  
 Job order number 2022012808/ 1  
 Job order date 04-05-2022  
 Service Advisor CHARMAINE KONG

Company  
 CHINA TAIPING INSURANCE (S) PL  
 3 ANSON ROAD  
 #18-00 SPRINGLEAF TOWER  
 Singapore 079909

Customer Details:  
 Company  
 3-D  
 PHOTOGRAPHY  
 562 ANG MO KIO AVENUE 3  
 #04-3491  
 Singapore 560562

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
2K5945106D	Reflector	1	pcs.	68.91	#1	68.91	73.73
	RHS REFLECTOR						
2K0813307	Rear Apron	1	pcs.	299.03	#1	299.03	319.96
	REAR END PANEL						
D 007500A2	Zinc Spray	1	pcs.	72.86	#1	72.86	77.96
D 180003M2	2k-Body Adhesive	1	pcs.	469.52	#1	469.52	502.39
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	66.78	#1	66.78	71.45
2K0863459H 82V	Cover For Lock Carrier Ti	1	pcs.	174.76	#1	174.76	186.99
	END PANEL TRIM COVER						
2K0863905 82V	Cap Titanium Black	4	pcs.	3.04	#1	12.16	13.01
701864445B	Speed Nut	4	pcs.	2.64	#1	10.56	11.30
2K0810972E	Wheelhouse Protector	1	pcs.	138.15	#1	138.15	147.82
	RHS REAR FENDER LINER						
	LABOUR	162	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINT	52	pcs.	800.00	#1	4,000.00	4,280.00
	R&R LHS REAR BOOT LID GLASS	1	pcs.	840.00	#1	840.00	898.80
	R&R RHS REAR BOOT LID GLASS	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER LHS BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER RHS BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	70 km/h STICKER	1	pcs.	12.00	#1	12.00	12.84
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00

Quotation valid till 11-05-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	22,366.37	7%	1,618.85	23,126.37	24,745.22
Total	760.00	22,366.37		1,618.85	23,126.37	24,745.22

Steve (LKK)  
 6/5/22, 11:30am

HL PL  
 P/P  
 by Bel  
 7 djs

Customer  
 LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

VISIT OUR WEBSITE: [after-sales.vw.com.sg](http://after-sales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](http://volkswagen.com.sg) and [www.skoda.com.sg](http://www.skoda.com.sg) (for additional services, products and promotions) - to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Service Advisor

VW KSWAGEN CENTRE SINGAPORE  
Alexandra Road  
Singapore 159934  
Reg. No.: 199101494Z  
ST No.: M200985052



Commercial  
Vehicles

## Quotation

Non binding - Preview

Page

3/3

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Company  
3-D  
PHOTOGRAPHY  
562 ANG MO KIO AVENUE 3  
#04-3491  
Singapore 560562

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

05-05-2022  
5211001170  
200208384E  
30001  
2022012808/ 1  
04-05-2022  
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
GBH2168X	SAAA26	19-03-2018	WV1ZZZ2KZHX157337	Caddy pan.vanBasic 75 CRD A6	26,809

All invoices are denominated in SGD, unless otherwise stated.

CHINA TAIPING  
VS  
CHINA TAIPING  
# 12808



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	04/05/2022 12:49 (SGT)
Date of Accident	29/04/2022 16:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE BEFORE AMK AVE 1 EXIT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH2168X

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	PHOTOGRAPHY 3-D
Company Reg No	5XXXX104C
Email Address	chungeeheng@hotmail.com
Mobile Phone No	(Phone) +65-94231973
Alternative Phone No	+65-94231973

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Caddy
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2000

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

#### DRIVER

Name of Driver	CHU NGEE HENG
NRIC No	SXXXX568C



Birth  
ation  
Or Driving Pass  
ing experience  
nder  
obile Number  
At. Phone Number  
Email Address  
Address

Address complement  
Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

01/09/1973

Indoor

02/08/2001

20 YEARS AND 8 MONTHS

Male

(Phone) +65-94231973

-

chungeeheng@hotmail.com

562 ANG MO KIO AVENUE 3

#04-3491

560562

No

OWNER OF COMPANY

No

-

-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Collision - Head to Rear

Clear

Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

2

No

-

Yes

1

No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

No

No

-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

Yes

No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

NRIC No

Contact Number

Address

SMK1108E

-

-

-

-

Private car

TAN BOON KEEM

SXXXX889E

-

-



complement  
Company Name  
Of Damage  
is of property damaged in accident  
Of Passenger (Including Driver)


-  
-  
-  
-  
1

## Describe Circumstances of the Accident

As I was driving along CTE south bound before Ang Mo Kio Ave 1 exit, a trailer slowed down in front of my van. I braked and slowed down too. Then I saw a white car, SMK 1108 E from my rear view mirror approaching fast towards my van and crashed into the rear of my van.

## Declaration

We declare the foregoing particulars are true in every respect.

  
4 May 2022

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

04 MAY 2022



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

### Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
4 May 2022  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
04 MAY 2022

### Sketch Plan

