

LOT :

Priority : NORMAL / URGENT

Reference No : 01/ABS22004169/RCC Claim No. \_\_\_\_\_From (Person) : 4/5/2022 of ABSDate/Time : Amber

IN OPS : Yes / No DOA:

Ref:

MV : \$

TYPE: M.Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Vehicle No : G8G7444X D.O.A / As At May 2022

Make &amp; Model: \_\_\_\_\_

NEW CAR PRICE: \$

Registration Date: \_\_\_\_\_

MV: \$ 50K Quote by: CKR

COE Expiry Date: \_\_\_\_\_

FS: \$ 45K Date \_\_\_\_\_

LTA Total Rebate Amount: (PARF) + (COE) = \_\_\_\_\_

SV: \$

## Calculation for LTA Rebate:

(a) COE Period: \_\_\_\_\_ X 12 = \_\_\_\_\_ Mths

As At: \_\_\_\_\_

= \_\_\_\_\_ Mths

= \_\_\_\_\_ Mths

(b) Balance Months: \_\_\_\_\_

(d) Residue COE : QP \_\_\_\_\_ X  $\frac{(b)}{(a)}$  = \_\_\_\_\_

(a) \_\_\_\_\_ - (b) \_\_\_\_\_ = \_\_\_\_\_ / 12 = \_\_\_\_\_ &lt; \_\_\_\_\_ yrs

Register Before/After MAY 2002

(e) PARF = (OMV) \_\_\_\_\_ X \_\_\_\_\_ X \_\_\_\_\_ = \_\_\_\_\_

LTA Total Rebate Amount: (d)+(e) \_\_\_\_\_

Salvage Value(LTA Rebate - 5%): \_\_\_\_\_

## Calculation for Valuation:

Average MV \_\_\_\_\_ \$

## Calculation for Repossessed vehicle:

High demand vehicle: Yes / No - \$

Parallel Import vehicle: Yes / No - \$

More than 10yrs old: Yes / No - \$

MV for Repossessed vehicle = \$

Engine Capacity: High / Low - \$

Europe / Asia Car - \$

Car Condition: Good/Fair/Poor/Burnt - \$

No. of transfer : - \$

Other deduction - \$

Forced Sales Value derived = \$

Date / Time

Action / Instruction

Additional Information:

G8G7444X-X

**Celine Fong (LKKAUTO)**

---

**From:** AMBER <amber@absfinancial.sg>  
**Sent:** Wednesday, 4 May 2022 1:50 PM  
**To:** Celine Fong (LKKAUTO)  
**Cc:** assignments; joanne@absfinancial.sg  
**Subject:** Inspect - PD381P & GBG7444X  
**Attachments:** PD381P PARF MAY.pdf; GBG7444X PARF MAY.pdf

Hi Celine,

Vehicles in 38M Penjuru road. Thank you.

Warmest Regards,

**Amber**

Hire Purchase Executive  
38M Penjuru Road (S) 609148

T : 6933 9391

F : 6456 0678



**ABS FINANCIAL PTE LTD**

**From:** AMBER [mailto:amber@absfinancial.sg]  
**Sent:** Monday, 4 April 2022 2:29 pm  
**To:** 'Celine Fong (LKKAUTO)' <celinefong@lkkauto.com>  
**Cc:** 'assignments' <assignments@lkkauto.com>; joanne@absfinancial.sg  
**Subject:** RE: Inspect-YQ2223A

Hi Celine,

Vehicle in 38M Penjuru road. Thank you.

Warmest Regards,

**Amber**

Hire Purchase Executive  
38M Penjuru Road (S) 609148

T : 6933 9391

F : 6456 0678



**ABS FINANCIAL PTE LTD**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 423B

### Vehicle Details

Vehicle No.: GBG7444X

Vehicle to be Exported: Yes

Intended Deregistration Date: 31 May 2022

Vehicle Make: TOYOTA

Vehicle Model: HIACE VAN TURBO 5DR MT

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 1KD2751718

Chassis No.: JTFHT02P300233804

Maximum Power Output: -

Open Market Value: \$28,138.00

Original Registration Date: 26 Oct 2017

First Registration Date: 26 Oct 2017

Transfer Count: 2

Actual ARF Paid: \$1,407.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 25 Oct 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$35,894.00

COE Rebate Amount: \$19,965.00

**Total Rebate Amount: \$19,965.00**

The information contained herein is correct as at 04 May 2022

OK

MV ~~50~~  
PS 45

05/11/13) Wef  
ASS. REC. BY: Pme

REF:

CV/ABS22004169/RCL

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

5B6 7444 X

at Workshop m/s

ABS

of

38, Pwthen RD

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

GB6 7444X

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HACE

C.C

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

146797

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT6HT02P300233804

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05/05/12

Survey held at

ABS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$