



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM22004174/Kpa3q2 Date: 27/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2291C	Veh. Inspected	SLF 7177D	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03ZYK	Excess (\$)	0.00	
Assign From		Assign Date	05/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200D (A)	c.c	1950	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2130132A268758	Colour	METALLIC BLACK	
Odometer	259340 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55Z R17	TOURADOR	7 mm	
L/H Front Tyre	225/55Z R17	TOURADOR	7 mm	
R/H Rear Tyre	225/55Z R17	TOURADOR	7 mm	
L/H Rear Tyre	225/55Z R17	TOURADOR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2022	Inspection Date	09/05/2022	
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	