



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004199/Kvy3s2	
			Date: 27/05/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	FBN 7822B	Veh. Inspected	SMK 4558U
	Policy No.	D22MTMC01001020	Coverage (\$)	0.00
	Claim No.	CMTD2201525/MYE	Excess (\$)	0.00
	Assign From	Irene Henry	Assign Date	06/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	RENAULT SCENIC (A)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	VF1RFA00462476808	Colour	METALLIC BLACK
	Odometer	184118 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/55 R20	GREENLANDER	9 mm
	L/H Front Tyre	195/55 R20	GREENLANDER	9 mm
	R/H Rear Tyre	195/55 R20	GREENLANDER	7 mm
	L/H Rear Tyre	195/55 R20	GREENLANDER	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	02/05/2022	Inspection Date	06/05/2022
	Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	