

ASS. REQ. BY:

REF:

SMO/22004199/KV

Menneth

ASSIGNMENT

Front:

Date:

Estimated Cost:

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

877K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

201K1

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMK 4558U Yr Regn: 04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Kia Scentic c.c. 1861

Colour:

Black AC: Insured / Std / NI / NA

Sp. Reading

184118 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VFIRFA 00462476808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

R: 195/55R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

2/5/22

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

6/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

P. R. S.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

LKK Kenneth

ESTIMATION REPORT

Vehicle No : SMK4558U
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00462476808
Year of Manufacture : 2019

Estimation No. : E21060015
Date : 05/05/2022

Not Authorised
Repair After paint
4 days
LKK &

No.	Code	Description	Qty	U/P	Amt
Section: Remark					
1		SOMPO INSURANCE SINGAPORE PTE LTD DOA: 2.5.2022 THIRD PARTY CLAIMS	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Parts

2	901523953R TAILGATE OUTER PANEL	1.00	949.28	R	949.28	X
3	908895927R REAR EMBLEM	1.00	229.39	nn	229.39	X
4	908924456R LOGO RENAULT	1.00	160.56	nn	160.56	—
5	908923255R LOGO SCENIC	1.00	181.44	nn	181.44	—
6	908886823R RIVET CLIPS	6.00	9.24		55.44	7
7	850221774R REAR BUMPER	1.00	1,482.96	Bu	1,482.96	✓
8	850189314R REAR BUMPER LOWER	1.00	689.72	Dell cm	689.72	✓
9	850703057R REAR BUMPER SLIVER MOULDING	1.00	785.68	cm	785.68	—
10	850429618R REAR BUMPER CENTER SUPPORT BRACKET	2.00	477.84	pu	955.68	X
11	253A44101R SENSOR	1.00	285.80	pu Red	1,143.20	4X X
12	284389618R BLIND SPOT SENSOR	2.00	457.92	ols Red	915.84	4X
13	850476580R REAR BUMPER CENTER BRACKET	1.00	117.36	pu	117.36	X
14	905700851R TAILGATE LOCK CATCHER	1.00	116.72	nn	116.72	X
15	240154998R REAR BUMPER HARDNESS	1.00	271.16	pu	271.16	X
16	756100714R REAR BUMPER REINFORCEMENT	1.00	685.68		685.68	7
17	REAR BUMPER LOWER REFLECTOR RH	1.00	415.20		415.20	7

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Continue on next page...

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMK4558U
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00462476808
Year of Manufacture : 2019

Estimation No. : E21060015
Date : 05/05/2022

No.	Code	Description	Qty	U/P	Amt
					Amt S\$ 9,155.31
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 9,155.31

Section: Special nett

18		REAR BUMPER CLIPS	<i>M</i> 6.00	7.00	42.00 ✓
					Amt S\$ 42.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 42.00

Section: Labour

19		TO PANEL BEATING, REALIGN AND DISMANTLE REAR BUMPER, TAILGATE PANEL AND ALL NECESSARY ETC.	1.00	1,600.00	1,600.00 <i>3501</i>
20		TO REMOVE & REFIX REAR REVERSE SENSOR.	1.00	280.00	280.00 <i>601</i>
21		TO APPLY ANTI RUST	1.00	200.00 <i>rr</i>	200.00 <i>X</i>
22		TO CHECK WIRING FOR PROPER FUNCTION	1.00	150.00	150.00 <i>151</i>
23		TO PUTTY & SPRAY PAINTING TAILGATE, REAR BUMPER AND ALL NECESSARY ETC.	1.00	1,200.00	1,200.00 <i>601</i>
					Amt S\$ 3,430.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 3,430.00

Remarks:

SOMPO INSURANCE SINGAPORE PTE LTD
DOA: 2.5.2022
THIRD PARTY CLAIMS

Total S\$ 12,627.31

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/05/2022 16:36 (SGT)
Date of Accident	02/05/2022 00:40 (SGT)
Exact Location of Accident	Near Ang Mo Kio CC, (Thur 7.30 PM, Master Aaron Huan 6th Dan),, entrance via AMK Street 22, Ave 1,, Singapore 569976
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK4558U
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	+65-86881311

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Scenic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1500


INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	MCF22A00000100
Cover Note Number	-

DRIVER

Name of Driver	TAN KIM LENG
----------------	--------------

SKETCH PLAN



VEHICLE A - SMK4558U
VEHICLE B - FBN7822E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was travelling along Amk St 22. However, I feel a impact from my rear, that is a motorbike FBN7822E hit into my rear right bumper. I had come down exchange particulars and there is no injury in that moment. That's all.

DECLARATION

I declare the foregoing particulars are true in every respect.

Driver's Signature

Driver's Signature

Reporting Centre Personnel's Signature

