



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22004208/Avy3m4 Date: 15/06/2022 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 7306U	Veh. Inspected	SJR 7759K
Policy No.		Coverage (\$)	0.00
Claim No.	C10015093/CD	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	06/05/2022
2. Vehicle Particulars & Condition			
Make & Model	CITROEN C4	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	VF7LC5FWF9Y532518	Colour	BLUE
Odometer	197212 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/05/2022	Inspection Date	06/05/2022
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	