

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

STRIDES AUTOMOTIVE SERVICES PTE LTD	
Code: SMR	COON
1. Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. SMB 1573S Veh. Inspected SMN 7635U  Policy No. Coverage (\$) 0.00  Claim No. BUS/05/22/5005 Excess (\$) 0.00  Assign From ASHLENE LEE Assign Date 06/05/2022  2. Vehicle Particulars & Condition  Make & Model TOYOTA WISH (A) c.c 1798  Engine No. HIDDEN Year of Reg. 2015  Chassis No. JTDGG20W80J002762 Colour METALLIC MARK Odometer 223913 KM Steering IN ORDER	OON
Insured Veh.   SMB 1573S   Veh. Inspected   SMN 7635U	OON
Policy No.   Coverage (\$)   0.00	OON
Claim No.         BUS/05/22/5005         Excess (\$)         0.00           Assign From         ASHLENE LEE         Assign Date         06/05/2022           Vehicle Particulars & Condition           Make & Model         TOYOTA WISH (A)         c.c         1798           Engine No.         HIDDEN         Year of Reg.         2015           Chassis No.         JTDGG20W80J002762         Colour         METALLIC MARG           Odometer         223913 KM         Steering         IN ORDER	OON
Assign From   ASHLENE LEE   Assign Date   06/05/2022	OON
Vehicle Particulars & Condition           Make & Model         TOYOTA WISH (A)         c.c         1798           Engine No.         HIDDEN         Year of Reg.         2015           Chassis No.         JTDGG20W80J002762         Colour         METALLIC MARG           Odometer         223913 KM         Steering         IN ORDER	OON
Make & Model         TOYOTA WISH (A)         c.c         1798           Engine No.         HIDDEN         Year of Reg.         2015           Chassis No.         JTDGG20W80J002762         Colour         METALLIC MARC           Odometer         223913 KM         Steering         IN ORDER	OON
Engine No. HIDDEN Year of Reg. 2015  Chassis No. JTDGG20W80J002762 Colour METALLIC MARG  Odometer 223913 KM Steering IN ORDER	:OON
Chassis No. JTDGG20W80J002762 Colour METALLIC MARG Odometer 223913 KM Steering IN ORDER	:OON
Odometer 223913 KM Steering IN ORDER	ROON
Joseph Market Control of the Control	
Desires IN ODDED Manuficture COORTS DIM	
Brakes IN ORDER Modification SPORTS RIM	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre         215/50 R17         ARIVO         6 mm	
<b>L/H Front Tyre</b> 215/50 R17 ARIVO 6 mm	
R/H Rear Tyre         215/50 R17         ARIVO         5 mm	
<b>L/H Rear Tyre</b> 215/50 R17 ARIVO 5 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 05/05/2022 Inspection Date 06/05/2022	
Survey held at OPTIMA WERKZ PTE LTD	
10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days	