

ASS. REC. BY: ThavanREF: CS/ICS22604214/4473

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STD65475 Yr Regn: 30/10/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Ionig c.c 1580Colour: blue A/C: Insured / Std / NI / NASp. Reading: 372272 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: hmt1c85/cv14187858Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 5/5/22 D.O.I. 6/5/22Survey held at CDGEDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

ELICS (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.05.2022

Jumar:

REPAIR ESTIMATE

Time: 13:43:46

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305514973
REGN NO : SHD6547J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 05.05.2022 10:15
ACCIDENT DATE : 05.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER#	1	481.10	20.00	384.88	/Cut
0002 04-01-0104-2835-G LAMP ASSY-HEAD LH#	1	2,110.30	20.00	1,688.24	/Cra
0003 04-01-0101-0111-G BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/NAC
0004 04-01-0104-3813-G EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28	/me
0005 04-01-0104-0574-G PANEL-FENDER LH#	1	588.80	20.00	471.04	/PT
0006 03-01-0104-2061-G CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	/Scr

SUB-TOTAL : 2,860.16

JOB NATURE

0000 PB	PANEL BEATING	1100.00	1250 700
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30
0003 17-01	CHECK ALL LIGHTING	50.00	30
0004 20-05	ADVERTISMENT STICKER-FENDER	100.00	/NAC

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305514973
REGN NO : SHD6547J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 05.05.2022 10:1
ACCIDENT DATE : 05.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,900.00

TOTAL : 4,760.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thuan
82235769
6/5/22 1645
P/p 3 days up

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 05.05.2022 13:37 Page : 1

am: ARC Repair TP(CLS0)1
OMER

JOB CARD Sales Order: 4203998

JOB NO 305514973

15 COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (C)
(P)

REG NO SHD6547J
MAKE HYUNDAI
MODEL IONIQ(G3)
YR OF MFG 30.10.2019
CHASSIS NO KMHC851CVLU187858


MILEAGE
FUEL
DATE TIME IN 05.05.2022 10:15
TARGET DATE
COMPLETION DATE

OUNT (LITRES)

JOB DESCRIPTION

ccident Date: 05.05.2022
ATURE: 3P 05.05.2022

/NO LABOR CODE DESCRIPTION



KEY & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHD6547J JU ECICE

Vehicle No. SHD6547J

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard