

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4505J

35.05.2022

MAKE REG 13.10.2016

MODEL HYU- I40

CHIANG/ AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER LOWER COVER			\$228.00
2	REAR BUMPER BRACKET SIDE /RH		\$35.60	\$35.60
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	TAIL LAMP RH			\$697.80
1	REAR WHEEL CAP			\$214.20
1	REAR FENDER RH			\$2,171.40
				\$3,922.00
				\$784.40
				\$3,137.60
1	REAR FENDER ADVERTISEMENT			\$100.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
				\$335.70
	Labour Charge			
	Panel Beating			\$850.00
	Spray Painting Charge			\$600.00
	Remove/Refix Upholstery			\$90.00
	Check lighting			\$60.00
	Tuff Kote			\$90.00
				\$1,690.00
				\$5,163.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thavan

82235769

6/5/22 1630

L/S 3dayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 06.05.2022 13:02

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4204169

JC NO.305515005

ISTOMER

VMS COMFORT TRANSPORTATION PTE LTD

ISTOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

L. (R) 65508755

(O)

(P)

SCOUNT CARD NO.

Handwritten signature

REGN NO.:

SHA4505J

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

06.05.2022 09:35

DATE/TIME IN

YR OF MANU.

13.10.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU095356

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 05.05.2022

NATURE: 3P 05.05.2022

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA4505J

CHIANG

Vehicle No.:

SHA4505J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard