

Date : 13.05.2022

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : **SHA4505J**

05.05.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: AXA SMS5150M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost

\$3,450.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Signature :

Name : CHIANG

Name :

Tel : 62148314

Date :

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: