

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ QD / ☐ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s PREMIUM AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess: 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$90k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW2202H

Yr Regn: 02 Feb/2018

Type ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI / A3 SEDAN 1.0 c.c 999

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 48944 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ8V3J1044214 *

Gen. Cond ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 205/55R16

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 06-05-2022

Survey held at W/S 10:30

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Yes/No BI Involved

15/11/22@4.59pm confirmed with Mr Boo final fig: \$19,425.16 and 14 days
(red, 11538.84, 37%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 18/11/22

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cost / MPB: 19,425.16