

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.04.2022

Time: 08:40:13

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305514405
 REGN NO : SHA4277S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 10.08.2017
 DATE/TIME IN : 29.04.2022 14:00
 ACCIDENT DATE : 29.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	REMARKS
0001	04-01-0302-2292-A	COVER FRONT BUMPER+#	1	586.16 25.00 439.62	X Repair
0002	04-01-0302-2267-G	BUMPER CLIPS	10	22.00 25.00 16.50	X NN
0003	04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	86.50 25.00 64.87	✓
				SUB-TOTAL	: 520.99

JOB NATURE

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	REMARKS
0000	PB	PANEL BEATING		400.00	350
0001	SP	SPRAYPAINT CHARGE		600.00	500
0002	17-01	CHECK ALL LIGHTING		50.00	X NN
0003	20-05	RENEW ADVERTISMENT STICKER-		100.00	✓
				SUB-TOTAL	: 1,150.00

TOTAL : 1,670.99

Juman:

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

~~1 Day~~ 2 Days

4/5

After repair photos.

Car Qip

04/5 11:30

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental claim must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: