

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Attention : Motor Claim Department

Contact : 6389 6111 (main) Fax No. : 6222 1033

Estimate : TP22-046

Date : 29/04/2022

Vehicle Num. : SKZ731G

Make/Model : Honda Vezel-2015

Chassis/Eng# : RU11108536/L15B4028539

Accident Date : 11/04/2022

Claim No. :

Reference :

Policy No. : (06/01/2023)

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LIST ITEMS :				
1.	1 pc	Rear Bumper Assy <i>new</i>		655.00 <i>+</i>
2.	10 pcs	Rear Bumper Clips <i>new</i>	4.50	45.00 <i>+</i>
3.	1 pc	Rear Bumper Side Holder LH <i>new</i>		37.50 <i>+</i>
4.	1 pc	Rear Fender LH <i>new</i>		931.80 <i>+</i>
5.	1 pc	Rear Fender Guard LH <i>new</i>		250.00 <i>+</i>
6.	1 pc	Side Rocker Skirt LH <i>new</i>		350.00 <i>+</i>
7.	1 pc	Rear Door LH <i>new</i>		930.60 <i>+</i>
8.	1 pc	Rear Door Mechanism Lock LH <i>new</i>		195.80 <i>+</i>
9.	1 pc	Rear Door Weatherstrip LH <i>new</i>		86.50 <i>+</i>
10.	1 pc	Frt Door LH <i>new</i>		950.00 <i>+</i>
11.	1 pc	Frt Door Weatherstrip LH <i>new</i>		153.80 <i>+</i>
12.	1 pc	Frt Fender LH <i>new</i>		521.70 <i>+</i>
13.	1 pc	Frt Fender Guard LH <i>new</i>		250.00 <i>+</i>
14.	1 pc	Rear Sport Rim LH <i>new</i>		938.00 <i>+</i>
List TotalSS :				6,295.70
25.00% Discount SS :				1,573.93
				4,721.77
LABOUR :				
To remove, rearrange electrical wirings, check lighting				80.00 <i>30</i>
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				1,200.00 <i>500</i>
To putty and respray painting on affected area.				1,500.00 <i>500</i>
Labour Total SS :				2,780.00

Total SS : 7,501.77

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin
L/S 10/05/22.

OA Dnp

total: 318448

L/S: 2550