

GBB 5934M. 2009 July.
Citroen Berlingo 1560 CC.
VF77B9H TC9 J095874

TP SMRT.
Denise.

Rear Bumper	Distorted	710.	✓
Rear Bumper Side Holder x 02	RH Damaged	52 x 2 = 104	✓ 52
Rear Bumper Reinforcement	Dented	472	✓
Rear Bumper tow Cover	Missing	45	✓
Rear End Panel	Dented	685	✓
Rear End Panel Top Garnish.	HP New	285	X
Rear End Panel Top Garnish Clips	HP	20 (SN)	X
Rear End Panel Sealant	New	60 (SN)	✓
Taillamp RH	Smashed	385.	✓
Taillamp Panel RH	Distorted	358	✓
Rear RH Door	Distorted	1359.	✓
Rear RH Door Lock Upper	HP	248	X
Rear RH Door Lock Centre	✓	354	✓
Rear RH Door Lock Lower	Damaged	259	✓

GBB5934M.

Reer RH Door Weatherstripe.	at	265	✓
Reer RH Door Inner Trim Board	del	269.	✓
Reer RH Door Inner Trim Board Caps.	^{new}	20(SN)	✓
Reer RH Door Hinge x 02 Best		221x2 = 4+2	✓
Reer RH Door Check	^{2nd}	159	✓
Reer RH Door Glass Moulding	} ^{new}	121	✓
Reer RH Door Glass Sealant.		50(SN)	✓
Bestlingo Wording	} ^{new}	75	✓
5 Pax Sticker		10(SN)	✓
Company Information Sticker	^{new}	200(SN) 150(SN)	
Reverse Sensor	^{Damaged}	280(SN) 200(SN)	
Reer RH Body Panel	^{Distorted}	1550	✓
Reer RH Body Panel Air Vent	^{Missing}	58	✓
Reer RH Body Panel Inner Trim Board	^{del.}	256	✓
Reer RH Body Panel Inner Trim Board Caps.	^{new}	30(SN)	✓

GBB5934M.

Rear RH Body Panel Inner Shield ^{to} 145 ✓
Rear RH Body Panel Inner Shield clips. ^{new} 30(SN) ✓
Rear RH Body Panel Advertisement Sticker ^{new} 400(SN) 200(SN)
Sliding Door Rail RH. ^{new} 241 ✓
Floor Panel. ^{Ry's} 3655 ✓
Rear RH Tyre. ^{new} 200(SN) ✓

8018

S.N: 850

7217.10.

GBB 5934 M.

Panel Beating

Spry Painting.

Wiring

To remove reverse sensor

To spry tuff coat

To remove upholstery.

To transfer door fittings.

To remove door g/s

~~2200~~ 1400

~~1400~~ 1200

~~50~~ 30

~~100~~ 50

~~180~~ 100

~~150~~ 60

~~150~~ 60

~~100~~ 50.

2950

18100

Total: 11017.10.

L/S: 8.51e (Nett Value)

10 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: